


ase

50749

Readers are forbidden to MU

11:









FOUR HUNDRED RECEIPTS

FOR

COLORS, PASTES, ACIDS, PULPS, BLUE VATS, LIQUORS, ETC. ETC.,

6562

FOR

COTTON AND WOOLLEN GOODS,

INCLUDING THE

CELEBRATED BARROW DELAINE COLORS.

4400

BY

JOHN SELLERS,

AN EXPERIENCED PRACTICAL WORKMAN.

#

PHILADELPHIA:
HENRY CAREY BAIRD,
INDUSTRIAL PUBLISHER,
406 Wallott Street.

1865

Entered according to Act of Congress, in the year 1865, by
HENRY CAREY BAIRD,

in the Clerk's Office of the District Court of the United States in and for the Eastern District of Pennsylvania.

PHILADELPHIA: COLLINS, PRINTER.

PREFACE.

The author, in presenting this volume to the trade, of which he is a member, would simply remark that he has aimed to make it purely practical, the receipts here given having resulted from a long-continued practice. None of these receipts having been included in this yolume without previously undergoing this test, with success, he feels certain that, well prepared, they must prove valuable to all who are engaged in the business.

October 1, 1865.

Digitized by the Internet Archive in 2013

				PAGE
No.	1.	1 Acid-Madder .		13
66	2.	2 Acid-Madder .		13
"	3.	3 Acid-Madder .		14
6.6	4.	5 Acid-Madder		14
"	5.	10 Acid-Madder .		14
66	6.	12 Acid-Madder .		15
4.6	7.	31 Acid—Madder .		15
4.6	8.	3 Chocolate—Madder		15
6.6	9.	4 Chocolate—Madder		16
"	10.	5 Chocolate—Madder		16
66	Î1.	6 Chocolate		16
6.6	12.	8 Chocolate		17
"	13.	Red for Gum Chocolate		17
"	14.	2 Gum Chocolate .		17
"	15.	4 Gum Chocolate—Madder		18
66	16.	New Black-Madder		18
6.6	17.	10 Black-Madder .		18
6.6	18.	4 V. Black—Madder		19
6.6	19.	G. Black-Madder .		19
£ 6	20.	4 lbs. Catechu Standard		19
6.6	21.	Sal Ammoniac Liquor		20
"	22.	Gum Brown Standard		20
"	23.	Dark 7 Brown-Madder		20
6 6	24.	41 Old Brown-Madder		21
6 6	25.	Acetic Acid for Brown		21
6 6	26.	31 Old Brown—Madder		21
"	27.	21 Old Brown-Madder		22

						PAGE
2	No.	28.	1 Light Y. Brown-Madder			22
	"	29.	2 Light Y. Brown .			22
	"	30	3 Light Y. Brown-Madder			23
	6.6	31.	4 Light Y. Brown-Madder			23
	6.6	32.	6 Light Y. Brown-Madder			23
	6 6	33.	31 R. Brown Paste-Madde	r.		24
	"	34.	9 Brown Paste—Madder			24
	"	35.	Dark Brown Paste-Madder			25
	6.6	36.	41 Brown Paste-Madder			25
	66	37.	2 A. Brown-Madder			23
	"	38.	32 Brown Paste—Madder			26
	"	39.	2 C. Brown-Madder			26
	"	40.	41 C. Brown-Madder			27
	6.6	41.	1 C. Brown-Madder			27
	4.6	42.	31 C. Brown .			27
	"	43.	X Standard			28
	"	44.	G. Orange-Madder .			28
	"	45	2 Orange-Madder .			29
	"	46.	Dark Drab-Madder			29
	6.6	47.	18 Dark Drab—Madder			29
	"	48.	1 Drab on 12 lbs. Drab-Ma	dder.		30
	4.4	49.	2 Drab—Madder .			30
	"	50.	3 Drab-Madder .			30
	66	51.	4 Madder Drab .			31
	"	52.	2 S. Drab—Garancine			31
	"	53.	2 R. Drab—Garancine			31
	44	54.	5 R. Drab—Garancine			32
	"	55.	5 Madder Drab-Garancine			32
	6.6	56.	8 Purple Paste-Madder			33
	"	57.	10 Purple Paste .			33
	"	58.	12 Purple Paste .			33
	66	59.	15 Purple Paste .			33
	44	60.	18 Purple Paste .			33
	66	61.	24 Purple Paste .			33
	4.6	62.	30 Purple Paste .			33
	٤٤	63.	40 Purple Paste .			33

		CONTENT	s.			VII
					-1	PAGE
No.	64.	50 Purple Paste .				33
4.6	65.	60 Purple Paste .		•		33
6.6	66.	70 Purple Paste .				33
46	67.	80 Purple Paste .				33
66	68.	100 Purple Paste .				3 3
66	69.	Gum Purple Standard	9			34
4.6	70.	Farina Standard .				34
"	71	24 Gum Purple—Madder				34
46	72.	15 Gum Purple .				35
4.6	73.	18 Gum Purple .				35
46	74.	20 Gum Purple .				35
46	75.	28 Gum Purple .		•		35
6.6	76.	30 Gum Purple .				35
66	77.	34 Gum Purple .				35
-6 6	78.	36 Gum Purple .				35
"	79.	40 Gum Purple .				35
46	80.	50 Gum Purple .				35
66	81.	70 Gum Purple .				35
66	82.	80 Gum Purple .	**			35
46	83.	100 Gum Purple .				35
4.6	84.	X Resist Red—Madder				35
4.6	85.	P. Red—Madder .				35
6.6	86.	S. Red-Madder .				36
44	87.	Dark Resist Red-Madder				36
6 6	88.	10 Red-Madder .			. `	37
66	89.	6 Light Red—Madder				37
4.4	90.	9 Light Red				38
6.6	91.	12 Light Red—Madder				38
66	92.	Light Resist Red—Madder				39
4 6	93.	11 Resist Red—Madder				39
46	94.	Dark Red Paste—Madder				40
66	95.	1 B. Red				40
6.6	96.	2 B. Red				40
66	97.	3 B. Red				40
4.6	98.	4 B. Red				40
; (99.	5 B. Red				40

No.	. 100.	6 B. Red .					40
6.6	101.	7 B. Red .					40
"	102.	8 B. Red .					40
"	103.	10 B. Red .					40
"	104.	12 B. Red .				,	40
"	105.	16 B. Red .					40
"	106.	Mordant for Blacks					41
"	107.	Padding Liquor					41
"	108.	Acid Standard for Bla	ick				41
"	109.	Strong V. Acid-Mad	der				42
66	110.	6 V. Acid-Madder					42
"	111.	2 Lavender for Red Pa	adding				42
6.6	112.	Oil for Colors			٠.		43
4.6	113.	Iron Mordant, old					43
"	114.	18 Shade—Madder					43
"	115.	New Black-Madder	Logwoo	d			44
"	116.	24 Gum Purple					44
"	117.	16 Resist Red-Madde	er				44
66	118.	Dark Resist Red	• ,				45
"	119.	P. Red-Madder					45
66	120.	10 Red-Madder					45
"	121.	9 Red-Madder					46
"	122.	O. Paste for Orange					46
66	123.	8 Purple Paste-Madd	ler				÷7
"	124.	Finishing Blue					47
"	125.	2 Lavender for Reds					48
"	126.	Dark Pink .					48
"	127.	1 Pink .					48
"	128.	2 Pink .					49
"	129.	9 Pale Red .					49
"	130.	12 Light Red					4.9
"	131.	Logwood Standard		•			50
"	132.	Acetic Acid for Brown	1				50
"	133.	Iron Mordant New .					50
66	134.	Light Resist Red					51
"	135.	Mordant for Blacks					51

		CONTENTS.		ix
				PAGE
No.	136.	Black Padding Liquer		51
66	137.	Impression Blue		52
"	138.	5 V. Black		52
6.6	139.	2 A. Brown		52
"	140.	41 Paste Brown		53
6.6	141.	1 C. Brown .		53
6.6	142.	32 P. Brown .		53
"	143.	Finishing Blue		54
"	144.	W. Black Woollen		54
46	145.	P. Blacks		55
4 6	146.	Twice D. Y. Brown		55
"	147.	4 X Black		55
6.6	148.	Purple Mordant		56
46	149.	15 S Purple Elizerine		56
4.6	150.	* 2 R. Drab Twice—Madder		56
"	151.	* 5 R. Drab Twice-Madder		57
4 6	152.	* 11 Resist Red Twice .		57
44	153.	* 4 M. Drab Twice		58
46	154.	X Oxide of Chrome Standard		58
6.6	155.	* 1 X Shade .		 59
4 6	156.	Oxide of Chrome Standard .	, ,	59
46	157.	2 Shade		59
66	158.	* 3 Black-Madder .		60
44	159.	* New Chocolate		60
46	160.	Pencil Blue Standard .		60
44	161.	P. Slate—Madder		61
46	162.	* 21 Slate—Garancine		61
46	163.	* Oil for Colors Twice .		61
46	164.	* 8 Fawn-Madder .		62
	165.	* 2 C. Brown-Madder		62
46	166.	* 8 New Chocolate-Madder		63
4.6	167.	* 15 New Chocolate-Madder	r .	63
46	168.			63
66	169.	* *		64
"	170.	P. Aluminate of Soda		64
66	171.	X Standard		65

					PAGE
No.	172.	Substitute for A. Red			65
66	173.	2 A. Red			65
\$ 6	174.	3 A. Red			66
"	175.	4 A. Red			66
6.6	176.	5 A. Red			66
6.6	176.	6 A. Red			66
6.6	176.	7 A. Red			66
	176.	8 A. Red			66
66	176.	9 A. Red			66
4.6	176.	10 A. Red			66
66	176.	12 A. Red			66
"	176.	16 A. Red			66
66	176.	2 A. Reds		4.	66
"	177.	15 Fawn-Garancine			67
66	178.	4 X Shade			67
6.6	179.	3 X Shade			67
66	180.	17 Stone-Garancine			68
66	181.	Ultramarine Blue-Steam			68
"	182.				68
66	183.			3	69
"	184.	Fast Green-Steam .			69
"	185.	X Standard for Nitrate of L	end		69
6 6	186.	Nitrate of Iron Pulp .			70
"	187.	Wollin Walker Black		-	70
6.6	188.	4 B. Drab Steam X .			70
6.6	189.	X Dark C. Buff Standard			71
"	190.	X 1 Steam Brown .			71
6.6	191.	X Orange			71
"	192.	Light Brown—Steam			72
4.6	193.	X Dark Purple Standard			72
6.6	194.	Dark Brown-Steam .			73
64	195.	X 1 P. Drab-Steam .			73
66		X Pad Blue-Steam .			74
		X Steam—Black .			74
6.6		X A. Chocolate-Steam			75
"	199.	Spirit Black-Steam .			75

			PAGE
No.	200.	X Dark Blue—Steam	76
66	201.	X Dark C. Drab—Steam	76
66	202.	X Gall Standard-Calico	77
"	203	X Dark Paste—Olive	77
66	204.	X 6 Paste—Olive	77
6 6	205.	X 6 Dark Green	78
	206.	X Pea-Green or 16 Green-Steam	78
6.6	207.	X Light Green—Steam	79
6.6		X 16 Dark C. Blue	79
66		X 16 Gum Blue-China Right	80
6 6	210.	X 4 Gum C. Blue	80
• •		Prussiate Tin Pulp	80
"	212.	■ Dark Fast Green	81
66	213.	Dark Fast Blue	81
66	214.	No. 1 Fast Blue	81
6 6	215.	No. 2 Fast Blue	82
"	216.	No. 3 Fast Blue	82
6.6	217.	No. 4 Fast Blue	82
66	218.	No. 6 Fast Blue	83
6.6	219.	12 C. Blue	83
66	220.	8 Gum Blue—China	83
4.6	221.	Scarlet Red-Woollen not so good	84
6.6	222.	Green for Woollen	84
66	223.	Acetate of Tin	85
6.6	224.	Steam Orange for Woollen	85
. 6	225.	Standard China Blue	86
6.6	226.	Red for Woollen	- 86
4.6	227.	Standard for Pad New Blue	86
6.6	228.	D. 4 P. Blue for Black Shade Woollen-Stean	a 87
6.4	229.	Dark Buff Paste 6 & 3 Standard—Steam .	87
66	230.	1 Buff Paste—Steam	. 87
66	231.	2 Buff Paste	88
6 +	232.	* 6 and 3 Buff Standard	88
	233.	* 1 Fast Buff	88
66	234.	* 2 Fast Buff	89
	235.	* 4 lb. Indigo—In the mill	89

No.	236.	4 B. Drab—Steam				89
"	237.	* No. 1 Blue-Vat				90
66	2 38.	No. 2 Blue Vat				90
66	239.	No. 3 Blue Vat				91
6.6	240.	No. 4 Blue Vat				91
6.6	241.	To Precipitate Pulp	-			91
66	242.					91
"	243.					92
6.6	244.	1 C. Black for Orange	es			92
"	245.	Ultramarine Blue, Li	ight			93
6.6	246.	Light Pink, Woollen				93
66	247.	X 6 Light C. Blue				94
66	248.	Oxide of Tin-For M	adder I	Pulp (Oranges	94
66	249.	*1 X Blue .				94
66	250.	4 lb. Lavender				95
"	251.	Red Liquor .				95
66	252.	* Dark Paste Orange		,		95
66	253.	* 1 Paste Orange				96
6.5	254.	9 Dark Orange				96
66	255.	* 2 Paste Orange				96
66	256.	* 4 Paste Orange				97
66	257.	8 Light Orange				97
6.6	2 58.	12 Light Orange				97
66	259.	* G. Orange or 4 Mac	lder Or	ange		98
6.6	260.	* 4 S. Orange				98
66	261.	47 Shade .				98
6.6	262.	* 2 Madder Orange				99
6.6	263.	* 1 P. Green	,			99
6.6	264.	16 G. C. Blue				99
6.6	265.	* Annotto Orange St	andard			100
66	266.	* 4 S. Orange Steam				100
6.6	267.	4 Paste Blue .				100
66	268.	* 8 Paste Blue				101
66	269.	10 Paste Blue				101
66	270.	* 2 Light Blue				101
66	271.	* 3 Light Blue				102

		CONTENTS.		xiii
				PAGE
	272.	* 5 Light Blue	•	102
6.6	273.	* 8 Light Blue	•	102
66	274.	S. N. Yellow—Royal	•	103
"	275.	X 1½ B. Purple Paste—Royal .	•	103
"	276.	1 New Brown Steam		104
"	277.	Acetate Tin		104
"	278.	R. Purple Standard—Steam		105
"	279.	3 Puce Steam		105
"	280.	8 Puce Steam		105
"	281.	5 M. Drab Twice—In Garancine .		106
6.6	282.	W. Red, Steam		106
6.6	283.	Dark Spirit-Pink Woollen		107
"	284.	Dark Spirit—Purple Standard .		107
"	2 85.	W. R. Orange—Steam		108
66	286.	No. 2. B. Chocolate—Steam .		108
66	287.	2 W. Orange N		109
66	288.	W. Myrtle Green-Steam		109
"	289.	W. Chocolate—Steam		110
"	290.	* 4 N. Brown		110
6 6	291.	* Light Ultramarine-Blue Steam .		111
66	292.	New Orange for Ultramarine .		111
"	293.	S. C. New Orange		112
"	294.	* Steam Brown Standard		112
66	295.	3½ F. Brown		112
"	296.	D. S. Blue New-Blue Royal-Steam		113
"	297.	Plum Shade—Steam		113
66	298.	N. 3 Yellow—Steam		114
	299.	2 Plum Shade—Steam		114
4.6	300.	3 W. Orange Last—Steam		115
	301.	C. Standard Yellow	•	115
66	302.	* N. 16 Green—Steam	•	116
66	303.	* Dark Green—Steam	`	116
6.6	304.		•	117
66	305.		•	117
6.6		Black for Woollen		118
66	307.	Dark Ultramarine Blue		118
	501.	Dark Orthaniarino Diuc		110

			PAGE
No. 308.	8 T. Paste		118
	* New Finishing—Blue		119
" 310.	Pad Blue for Printing—Steam .		119
" 311.	5 New Chocolate—Steam	1	120
	* * 12 China Last—Blue		120
" 313.	W. Orange—Steam		121
" 314.	* 41 P. Blue		121
	* Wood Red-Steam		122
" 316.	R. B. Paste Standard		122
" 317.	R. B. Paste	•	122
	DELAINE COLORS.		
	DONE AT BARROW.		
No. 1.	Delaine Black for Black and Lavenders, &	c.	123
· · 2.	Delaine Yellow		124
" 3.	Delaine Dark Blue		124
" 4.	Tin Pulp		125
" 5.	Delaine Dark Green		125
" 6.	Strong P. Red		126
" 7.	A Very Good Delaine Chocolate. No. 1		126
" 8.	No. 2 Chocolate, Good for Light Delaines		127
" 9.	Delaine Chocolate Dark		127
" 10.	Delaine Pale R. R. Chocolate .		128
" 11.	Delaine R. R. Chocolate		129
" 12.	Delaine Dark Chocolate B		129
" 13.	Yellow Standard for Light Green Standard	١.	130
" 14.	Blue Standard for Green Standard .		130
" 15.	Delaine Pale Green Standard .		131
" 16.	Delaine Pale Green Color No. 3, 31.		131
" 17.	Delaine Green Light 1, 2		131
" 18.	Delaine Pale Blue		132
" 19.			132
" 20.	Delaine Orange (No. 1)		133

		CONT	ENTS.	•			ΧV
							PAGE
	21.	Another Orange (No		•		•	133
6.6	44.	Delaine Brown Stan	dard	•			134
"	23.	No. 3 Brown	•				134
61	24.	Another Brown Stan	dard				135
"	2 5.	No. 4 Brown	•	•	•		135
"	26.	Another Brown Stan	dard	•			136
"	27.	Light Brown	•	•			136
"	2 8.	Y. Brown Standard					136
"	29.	Y. Brown .	•				137
"	30.	Wood Color					137
"	31.	Black for Light Dela	ine				137
"	32.	Purple Standard					138
"	33.	No. 12 Purple					138
64	34.	No. 16 Purple					138
"	35.	No. 7 Purple					138
6 6	36.	Dark Purple					139
"	37.	Lavender .					139
"	38.	No. 8 Red .					139
"	39.	Black for Black and	White				140
"	40.	Another Good Black	:				140
6.6	41.	Another Black	٠.				141
"	42.	Pink .					141
"	43.	Drab Standard-B.	Standa	rd			142
"	44.	Y. Standard					142
6 6	45.	No. 7 Drab .					142
"	46.	Pale Blue .					143
"	47.	B. Green Standard					143
"	48.	B. Green Color					143
"	49.	B. Liquor .					144
"	50.	Drab Standard					144
"	51.	Dark Drab .					144
"	52.	No. 16 Drab					145
"	53.	No. 11 Drab					145
"	54.	No. 10 Drab					145
6.6	55.	Gum Substitute					145
6.6	56.	Gum Senegal					146

							PAGE
No.	57.	Blue Standard for P	adding				146
6.6	58.	Blue for Padding					146
6.6	59.	Pale Red for Dark I	Red				146
6.6	60.	Dark Red .		. "			147
						7	
		MADDET		ODG			
MADDER COLORS.							
No.	1.	Black .					149
"	2.	Madder Tin Red					149
"	3.	No. 15 Acid					150
"	4.	No. 40 Acid					150
66	5.	Black and White A	eid			-	150
6.6	6.	No. 2 Chocolate					151
"	7.	No. 3 Chocolate					151
"	8.	No. 12 Chocolate					151
"	9.	No. 8 Purple					152
"	10.	No. 32 Purple					152
"	11.	Catechu Brown					153
66	12.	Acetate of Copper					153
"	13.	No. 12 Red .					153
"	14.	Red Standard					154
"	15.	No. 8 Pink		i.			154
"	16.	Acid for Cutting Pi	nks				154
"	17.	Red Paste for Block		•			154
	16.	Tiou I asie for Diver	21115				LUT



50249

COLOR MIXER.

No. 1. 1 ACID.

MADDER.

2½ gallons Lemon Juice 60° Twaddle
1 gallon Caustic Soda 74° "
5 lbs. No. 3 Gum Subte. heated 180° F.
Add 3 gallons of Subte. Water.
Mix and strain.

No. 2.

2 ACID.

MADDER.

3 gallons Lemon Juice 60° Twaddle
1 gallon Caustic Soda 70° "
8 gallons Subte. Water.
Mix and strain.

No. 3.

3 ACID.

MADDER.

3 gallons Lemon Juice 60° Twaddle1 gallon Caustic Soda 70° "Mix and strain.

No. 4.

5 ACID.

MADDER.

1½ gallon Lemon Juice 60° Twaddle
½ " Caustic Soda 70° "
10 gallons Subte. Water.
Mix and strain.

No. 5.

10 ACID.

MADDER.

2 gallons Lemon Juice 60° Twaddle8 "Subte. Water.Mix and strain.

No. 6.

12 ACID.

MADDER.

2 gallons Lemon Juice 60° Twaddle6 "Subte. Water.Mix and strain.

No. 7.

31 ACID.

MADDER.

12 gallons Lemon Juice 60° Twaddle
4 " Caustic Soda 70° "
36 lbs. No. 3 Gum Subte. heated 180° F.
Mix and strain.

No. 8. 3 CHOCOLATE.

MADDER.

1½ gallon Water
1½ " Red L

1½ " Red Liquor 16° Twaddle

1 " Iron Liquor 24° "

6 lbs. of Flour or Starch. Boil and strain. No. 9.

4 CHOCOLATE.

MADDER.

2 gallons Water
2 "Red Liquor 16° Twaddle
1 gallon Iron Liquor 24° "
10 lbs. Starch.
Boil and strain.

No. 10. 5 CHOCOLATE.

MADDER.

2½ gallons Water
2½ "Red Liquor 16° Twaddle
1 gallon Iron Liquor 14° "
12 lbs. New Flour.
Boil and strain.

No. 11. 6 CHOCOLATE.

3 gallons Water
3 "Red Liquor 16° Twaddle
1 gallon Iron Liquor 24° "Thicken, boil, and strain.

No. 12.

8 CHOCOLATE.

4 gallons Water
4 "Red Liquor 16° Twaddle
1 gallon Iron Liquor 24° "Thicken, boil, and strain.

12 Chocolate, 15 Chocolate, 20 Chocolate, 24 Chocolate, 30 Chocolate, and 40 Chocolate, prepared on the same principle.

No. 13.

RED for GUM CHOCOLATE.

4 gallons Red Liquor 16° Twaddle8 lbs. ground Gum Senegal.Dissolve warm, and strain.

No. 14.

2 GUM CHOCOLATE.

1 gallon Red standard

1 " Iron Liquor 24° Twaddle

1 "Gum Water.
Mix and strain.

No. 15.

4 GUM CHOCOLATE.

MADDER.

2 gallons Red standard
1 gallon Iron Liquor 24° Twaddle
2 gallons Gum Water.
Mix and strain.

No. 16.

NEW BLACK.

MADDER.

2 gallons Red Liquor 16° Twaddle 2 " Iron Liquor 24° " 4 " Water 12 lbs. Starch.

Boil and strain.

No. 17.

10 BLACK.

MADDER.

3 gallons Iron Liquor 24° Twaddle
4 " Water
14 lbs. Starch.
Boil and strain.

No. 18.

4 V. BLACK.

MADDER.

3 gallons Water

1 gallon Iron Liquor 24° Twaddle

8 lbs. Starch.

Boil and strain.

No. 19.

G. BLACK.

MADDER.

2 gallons Water

2 " Logwood Liquor 8° Twaddle

5 " Pyroligneous Acid 6° "

2 " Iron Liquor 24° Twaddle

12 lbs. Starch.

Boil and strain.

No. 20.

4 LBS. CATECHU STANDARD.

120 gallons Water

400 lbs. Catechu

Boil 8 hours by fire and measure to 90 gallons; and add

10 gallons Acetic Acid for Brown.

Let settle all night. Use clear liquor standard 24° Twaddle.

No. 21.

SAL AMMONIAC LIQUOR.

96 gallons Water 4 lbs. Catechu standard 192 lbs. Sal Ammoniac.

Dissolve at 212° F., and let settle all night. Use clear liquor.

No. 22.

GUM BROWN STANDARD.

460 lbs. Gum Senegal.

Dissolve 80 gallons of Sal Ammoniac standard; heat, and let stand over night.

No. 23.

DARK 7 BROWN.

MADDER.

4 gallons Gum Brown

1 gallon Acetate of Copper 16° Twaddle.
Mix and strain.

.No. 24. 41 OLD BROWN.

MADDER.

8 gallons Gum Brown

1 gallon Acetic Acid for Brown

1 gallon Gum Water

2 gallons Acetate of Copper 16° Twaddle. Mix and strain.

No. 25.

ACETIC ACID for BROWN.

80 gallons Pyroligneous Acid 6° Twaddle 10 lbs. Yellow Prussiate of Potash

5 lbs. White Sugar of Lead.

Boil 5 minutes, and let settle one night. Use clear liquor.

No. 26.

31 OLD BROWN.

MADDER.

6 gallons Gum Brown

3 gallons Sal Ammoniac standard

1 gallon Acetic Acid for Brown

 $2\frac{1}{4}$ gallons Acetate of Copper 16° Twaddle

2 gallons Gum Water.

Mix, strain, and let settle one night. To be washed 3 times over in the tubs.

No. 27. 21 OLD BROWN.

MADDER.

6 gallons Gum Brown standard

2 gallons Sal Ammoniac standard

1 gallon Acetate of Copper 16° Twaddle

3 gallons Gum Water.

Mix and strain.

No. 23.

1 LIGHT Y. BROWN.

MADDER.

4 gallons Gum Brown

4 " Sal Ammoniae standard

1½ " Acetic Acid 6° Twaddle

61 " Gum Water

2½ "Acetate of Copper 16° Twaddle.
Mix and strain.

No. 29.

2 LIGHT Y. BROWN.

2 gallons Sal Ammoniac standard

3 gallon Acetic Acid 6° Twaddle for Brown

" Gum Water

3/4 " Acetate Copper 16° Twaddle. Mix and strain. No. 30.

3 LIGHT Y. BROWN.

MADDER.

4 gallons Sal Ammoniac standard

11 " Acetic Acid 6° Twaddle for Brown

11 " Gum Water

13/4 " Acetate Copper 16° Twaddle. Mix and strain.

No. 31.

4 LIGHT Y. BROWN.

MADDER.

2 gallons Sal Ammoniac Standard

1 gallon Acetic Acid 6° Twaddle for Brown

7 gallons of Gum Water

1 gallon Acetate of Copper 16° Twaddle. Mix and strain.

No. 32.

6 LIGHT Y. BROWN.

MADDER.

2 gallons Sal Ammoniae standard
1½ gallon Acetic Acid for Brown
10½ gallons Gum Water
1¼ gallon Acetate of Copper 16° Twaddle.
Mix and strain.

No. 33.

31 R. BROWN PASTE.

MADDER.

12 gallons Sal Ammoniac standard

3 "Water

3 "Red Liquor 16° Twaddle

1 gallon Acetic Acid for Brown

31 lbs. Starch.

Boil and add

3 gallons Acetate of Copper 16° Twaddle. Mix and strain.

No. 34. 9 BROWN PASTE.

MADDER.

8 gallons Sal Ammoniac standard

12 lbs. Starch.

Boil and add

2 gallons Acetate of Copper 16° Twaddle. Mix well, and strain. No. 35.

DARK BROWN PASTE.

MADDER.

8 gallons Sal Ammoniae standard 12 lbs. Starch.

Boil and add

1 gallon Acetate of Copper 16° Twaddle. Mix well, and strain.

No. 36. 41 BROWN PASTE.

MADDER.

8 gallons C. standard

1 gallon Acetic Acid

1 " Water

11 lb. Sal Ammoniac ground

14 lbs. new Flour.

Boil, and add

1 gallon Acetate of Copper 16° Twaddle. Mix and strain. No. 37.

2 A. BROWN.

MADDER.

4 gallons Gum Brown standard 1 gallon Gum Water

¹/₂ " Acetate of Copper 16° Twaddle. Mix well, and strain.

No. 38.

32 BROWN PASTE.

MADDER.

6 gallons Sal Ammoniac standard 1 gallon Acetic Acid for Brown

1 "Water

12 lbs. new Flour.

Boil, and add

1 gallon Acetate of Copper 6° Twaddle. Mix and strain.

No. 39.

2 C. BROWN.

MADDER.

4 gallons X standard.
Thicken with

6 lbs. of Gum substitute heated 180° F.

4 gallons Gum Brown

1 gallon Acetate of Copper 16° Twaddle. Mix and strain. No. 40.

41 C. BROWN.

MADDER.

5 gallons Gum Brown standard

2 "Sal Ammoniac standard

1 gallon X standard

2 gallons Acetate of Copper 16° Twaddle. Mix well and strain.

No. 41.

1 C. BROWN.

MADDER.

7 gallons Gum Brown standard

1 gallon X standard 10° Twaddle

1 " Acetate of Copper 16° Twaddle.
Mix well and strain.

No. 42.

31 C. BROWN.

6 gallons Gum Brown

3 "Sal Ammoniac

1 gallon X standard 10° Twaddle

3 gallons Gum Water

1½ gallon Acetate of Copper 16° Twaddle. Strain.

No. 43.

X STANDARD.

8 lbs. Alum dissolved in 4 gallons hot Water. Add

 $7\frac{1}{2}$ lbs. Common Soda.

Dissolve in 2 gallons hot Water, and add your Soda to your Alum by degrees. Wash three times. Filter, and put in a pan. Add 1 quart of Muriatic Acid 36° Twaddle, and boil down to 2 gallons standard 10° Twaddle, and run through a calico cloth, and use the clear liquor.

No. 44.

G. ORANGE.

MADDER.

4 gallons Bark Liquor 16° Twaddle

6 lbs. Gum Starch

4 " Sal Ammoniac

1 quart X standard 10° Twaddle. Boil, and half cool, and add

8 lbs. of Muriate of Tin Crystals. Mix and strain.

No. 45.

2 ORANGE.

MADDER.

- 4 gallons Bark Liquor 16° Twaddle
- 4 lbs. Gum Starch. Boil and add
- .2 quarts X standard 10° Twaddle
 - 1 quart Oxide of Tin Salts
- 6 lbs. Muriate of Tin crystals. Mix and strain.

No. 46.

DARK DRAB.

MADDER.

4 gallons Gum Brown

1 gallon Muriate of Iron 16° Twaddle

14 " Acetate of Copper 16° Twaddle.
Mix and strain.

No. 47.

18 DARK DRAB.

MADDER.

1 gallon Dark Madder Drab

1 " 1 Madder Drab.

Mix and strain.

No. 48.

1 DRAB on 12 LBS. DRAB.

MADDER.

5 gallons C. Brown standard
1 gallon Nitrate of Iron 20° Twaddle
5 quarts Acetate of Copper 16° Twaddle
5 gallons Gum Water.
Mix and strain.

No. 49.

2 DRAB.

MADDER.

6 gallons C. Brown standard
1 gallon Nitrate of Iron 20° Twaddle
2 gallons Acetate of Copper 16° Twaddle
10 "Gum Water.
Mix and strain.

No. 50.

3 DRAB.

MADDER.

9 quarts Sal Ammoniac standard 1 quart Nitrate of Iron 20° Twaddle 4 quarts Acetate of Copper 16° Twaddle 30 " Gum Water.

No. 51.

4 MADDER DRAB.

3 measures Sal Ammoniac standard

24 " Gum Water

1 measure Sumach Liquor 10° Twaddle

1 " 4 lbs. Lavender

1 " Acetate of Copper 16° Twaddle. Mix and strain.

No. 52.

2 S. DRAB.

GARANCINE.

3 gallons Sal Ammoniac standard
1 gallon Sumach Liquor 10° Twaddle
12 gallons Substitute Water
1 gallon 4 lbs. Lavender
1 " Iron Liquor 24° Twaddle
1½ " Acetate of Copper 16° Twaddle.
Mix and strain.

No. 53.

2 R. DRAB.

GARANCINE.

9 quart's Sal Ammoniac standard
2 "Muriate of Iron 20° Twaddle
½ quart Red Liquor 16° Twaddle
2 quarts Acetate of Copper 16° Twaddle
10 "Gum Water.

Mix and strain.

No. 54.

5 R. DRAB.

GARANCINE.

4 gallons Sal Ammoniac standard
1 gallon Red Liquor 16° Twaddle
1 " Iron Liquor 24° "
7 gallons Gum Water.
 Mix, strain, and add
1 gallon Acetate of Copper 16° Twaddle.

No. 55.

5 MADDER DRAB.

GARANCINE.

3 quarts Sal Ammoniae standard
1 quart Iron Liquor 24° Twaddle
1 " Sumach 10° Twaddle
1 " 4 lbs. Lavender
3 quarts Acetate of Copper 16° Twaddle
30 " Gum Water.
Mix and strain.

No. 56. 8 PURPLE PASTE.

MADDER.

7 gallons Water
1 gallon Fixing Liquor 42° Twaddle
1 " Iron Liquor 24° Twaddle
13 lbs. new Flour.
Boil and strain.

No.	57.	10	PURPLE	PASTE	; 9 g	alls.	water.
"	58.	12	"	"	11	ш	"
"	59.	15	"	ш	14	"	u
66	60.	18	. "	"	17	"	"
"	61.	24	"	ιι	23	"	"
"	62.	30	"	"	29	iı	"
"	63.	40	u	"	39	"	u
"	64.	50	u	u	49	"	u
"	65.	60	"	ll.	- 59	"	"
cc	66.	70	u	ii.	69	"	cc .
"	67.	80	. "	٠((79	u	"
"	68.	100	"	"	99 -	"	"

Other ingredients in the foregoing same as in 8 Purple.

No. 69.

GUM PURPLE STANDARD.

7 gallons Water
1 gallon Fixing Liquor 42° Twaddle.
Mix well.
Should stand 6° Twaddle.

No. 70.

FARINA STANDARD.

44 gallons Water.

Dissolve 550 lbs. Farina, and measure off to 88 gallons. Add

12 gallons Fixing Liquor 42° Twaddle.

Put in a tub, strain well, and let stand all night.

No. 71.

24 GUM PURPLE.

MADDER.

gallon Iron Liquor 24° Twaddle
 gallons Farina standard
 "Fixing Liquor 6° Twaddle.
 Mix well and strain.

No.	72.	15	Gum	PURPLE;	11	gal.	Farina	stand
"	73.	18	"	"	14	"	u	"
"	74.	20	"	"	16	"	"	"
"	75.	28	"	ii	24	"	ш	"
"	76.	30	"	"	26	"	"	"
"	77.	34	u	"	30	66	"	"
"	78.	36	46	"	32	"	"	"
"	79.	40	"	"	36	"	"	"
"	80.	50	"	ш	46	"	"	"
"	81.	70	"	"	66	"	"	- 66
. "	82.	80	"	"	76	"	"	"
"	83.	100	"	"	96	"	"	"

Other ingredients the same as 24 Gum Purple. These are all the Gum Purple shades.

No. 84.

50249

X RESIST RED.

MADDER.

12 gallons best Red Liquor 16° Twaddle 34 lbs. Flour.

Boil and add

12 lbs. Muriate of Tin Crystals.

Mix well and strain.

1 pint Bark Liquor 8° Twaddle.

No. 85.

P. RED.

MADDER.

6 gallons Red Liquor 16° Twaddle

12 lbs. Starch Flour.

Boil and add

1 pint Muriate of Tin 120° Twaddle. Mix well and strain.

Seat in with Japan Liquor at 8° Twaddle.

No. 86.

S. RED.

MADDER.

5 gallons Red Liquor 16° Twaddle same as before; boil and add

1 gill Muriate of Tin 120° Twaddle.

Mix and strain.

Seat in with Japan Liquor 8° Twaddle.

No. 87.

DARK RESIST RED.

MADDER.

4 gallons Red Liquor 16° Twaddle

8 lbs. Flour.

Boil and add

1½ lb. Muriate of Tin Crystals.

Mix and strain.

Seat in with 1 pint Japan Liquor 8° Twaddle.

No. 88.

10 RED.

MADDER.

6 gallons Red Liquor 16° Twaddle

2 " Water

16 lbs. Flour and Starch mixed.

Boil and add

1 gill Muriate of Tin 120° Twaddle. Seat it with Japan Liquor 8° Twaddle. Mix and strain.

No. 89.

6 LIGHT RED.

MADDER.

6 gallons Water
1 gallon Red Liquor 16° Twaddle
10 lbs. Flour.

Boil and add

7 lbs. Muriate of Tin Crystals.

Mix and strain.

Seat in with 1 gill Japan Liquor 8° Twaddle.

No. 90.

9 LIGHT RED.

1 gallon best Red Liquor 16° Twaddle 9 gallons Water

18 lbs. Flour.

Boil and add

20 oz. Muriate of Tin Crystals.

Mix and strain.

Seat in with 1 pint Bark Liquor 8° Twaddle.

No. 91.

12 LIGHT RED.

MADDER.

1 gallon Red Liquor 16° Twaddle

12 gallons Water

26 lbs. Flour.

Boil and add

13 oz. Muriate of Tin Crystals.

Mix and strain.

Seat in with 3 gills Bark Liquor 8° Twaddle.

No. 92.

LIGHT RESIST RED.

MADDER.

8 gallons Water

2 " Red Liquor 16° Twaddle

20 lbs. Flour.

Boil and add

3 lbs. 12 oz. Muriate of Tin Crystals.

Mix and strain.

Seat in with Japan Liquor 8° Twaddle.

No. 93.

11 RESIST RED.

MADDER.

12 gallons Red Liquor 16° Twaddle

24 lbs. Flour.

Boil and add

10 oz. Muriate of Tin Crystals.

Mix and strain.

Per gallon seat in with 1 quart Japan Liquor 8° Twaddle.

No. 94.

DARK RED PASTE.

MADDER.

12 gallons Red Liquor 16° Twaddle 24 lbs. Flour.

Boil and strain.

Seat in with 2 qts. Japan Liquor 8° Twaddle.

No. 95.

1 B. RED.

1 gallon Water

1 "Red Liquor 16° Twaddle

3 lbs. White British Gum.

Boil and add

1 oz. Muriate of Tin Crystals.

Mix and strain.

Seat in with Japan Liquor 8° Twaddle.

No. 96. 2 B. Red. No. 101. 7 B. Red.

" 97. 3 B. Red. " 102. 8 B. Red.

" 98. 4 B. Red. " 103. 10 B. Red.

" 99. 5 B. Red. " 104. 12 B. Red.

" 100. 6 B. Red. " 105. 16 B. Red.

Reduce these according to shade desired.

No. 106.

MORDANT for BLACKS.

32 gallons Water

73 lbs. Acetate of Lime. Dissolve

27 lbs. Copperas

64 " Alum.

Let settle and filter off. Should stand 18° Twaddle.

No. 107.

50249

PADDING LIQUOR.

18 gallons Mordant for Black

18 " Red Liquor 16° Twaddle

4 " Pyroligneous Acid 6° Twaddle

40 "Water.

Stir up well. It should stand 8° Twaddle.

No. 108.

ACID STANDARD for BLACK.

4 gallons Water. Dissolve

12 lbs. Sulphate of Potash. Add

8 gallons Lemon Juice 60° Twaddle Mix and filter; use clear liquor.

4*.

No. 109.

STRONG V. ACID.

MADDER.

4 gallons above Standard6 lbs. Starch.Boil and strain.

No. 110.

6 V. ACID.

MADDER.

4 gallons above Standard
6 lbs. Starch.
Boil and add
1½ lb. Oxalic Acid.
Dissolve and strain.

No. 111.

2 LAVENDER for RED PADDING.

20 lbs. Sulphate of Potash.
Dissolve in 2 gallons Water, and add
14 gallons Substitute Water. And add
1 quart Oxymuriate of Tin 120° Twaddle.
Mix well, and strain.

No. 112.

OIL for COLORS.

90 lbs. Palm Oil
10 gallons Gallipoli Oil
10 lbs. good Tallow
5 quarts Spirits of Turpentine.
Dissolve and strain.

No. 113.

IRON MORDANT, OLD.

24 gallons Iron Liquor 24° Twaddle
12 " Vinegar 4° Twaddle
4 lbs. Red Prussiate

4 " Nitrate of Potash

4 " Nitrate of lead.

Boil one hour, and let settle one night.

No. 114. 18 SHADE.

1 gallon Muriate of Iron 64° Twaddle3 gallons Substitute Water.Mix and strain.

No. 115.

NEW BLACK.

*MADDER LOGWOOD.

2 gallons Water

1 gallon Red Liquor 16° Twaddle

1 " Iron Liquor 24° "

6 lbs. Starch.

Boil and strain.

No. 116.

24 GUM PURPLE.

2 gallons Farina Standard

4 "Fixing Liquor 6° Twaddle

1 gallon Seated Iron 22° Twaddle. Strain.

No. 117.

16 RESIST RED.

MADDER.

- 2 gallons Red Liquor 16° Twaddle
- 6 lbs. Flour.

Boil and put in

2 lbs. Muriate of Tin Crystals. Strain. No. 118.

DARK RESIST RED.

4 gallons Red Liquor 16° Twaddle
8 lbs. Flour.
Boil and add
1½ lb. Muriate of Tin Crystals.

Strain and add 1 pint Japan Liquor at 8° Twaddle.

No. 119.

P. RED.

MADDER.

6 gallons Red Liquor 16° Twaddle15 lbs. Flour. Boil and add1 pint Muriate of Tin 120° Twaddle.Mix and strain.

No. 120.

10 RED.

MADDER.

2 gallons Water

6 "Red Liquor 16° Twaddle

18 lbs. Flour.

Boil and add 1 gill Muriate of Tin 120° Twaddle. No. 121.

9 RED.

MADDER.

2 gallons Water

6 "Red Liquor 16° Twaddle

18 lbs. Flour.

Boil and strain.

No. 122.

O. PASTE for ORANGE.

1 gallon Juice Liquor 52° Twaddle

3 lbs. Substitute Water.

Boil and add

2 lbs. Sulphate of Zinc. Dissolve and add

1 quart Substitute Water

8 oz. Chlorate of Potash. Mix and strain.

No. 123.

8 PURPLE PASTE.

MADDER.

1 gallon Iron Mordant 22° Twaddle 8 gallons Fixing Purple Liquor 6° Twaddle 15 lbs. Gum Starch.

Seat in with 1 pint Logwood Liquor 10° Twaddle.

Boil and strain.

No. 124.

FINISHING BLUE.

18 gallons Water. Dissolve

21 lbs. Yellow Prussiate

4 gallons Iron Liquor 24° Twaddle

3 gallon Oxymuriate of Tin 120° Twaddle

5 quarts Water

6 lbs. best Chrome.

Dissolve in 5 gallons Hot Water

1½ lb. Oxalic acid.

Dissolve in 1 gallon Hot Water.

Add 18 gallons Water.

Ready for use.

No. 125.

2 LAVENDER for REDS.

2 quarts Hot Water
2½ lbs. Supersulphate of Potash
6 quarts of Gum Substitute.
Thicken and add
1 noggin Oxymuriate of Tin
1 " Muriate of Tin 120° Twaddle.
Mix and strain

No. 126. DARK PINK.

4 gallons Standard1 gallon Subte. Water.Mix and strain.

No. 127.

1 PINK.

gallon Standard
 " Gum Subte. Water.
 Mix and strain.

No. 128.

2 PINK.

2 gallons Standard

4 " Gum Subte. Water.

Mix and strain.

Reduce the other Pinks according to number, as you want them.

No. 129.

50249

9 PALE RED.

1 gallon best Red Liquor 16° Twaddle

18 lbs. Flour

9 gallons Water

10 oz. of Muriate of Tin Crystals.

Mix and strain.

1 pint Bark Liquor 8° Twaddle.

No. 130.

12 LIGHT RED.

1 gallon best Red Liquor 16° Twaddle

12 gallons Water, boiled

26 lbs. Flour

13 oz. Muriate of Tin Crystals.

Mix and strain.

3 gills Bark Liquor 8° Twaddle.

5

No. 131.

LOGWOOD STANDARD.

24 gallons Logwood 8° Twaddle
8 " Hot Water
1 lb. Chloride of Potash dissolved
1 lb. Sal Ammoniac dissolved.
Let settle.

No. 132.

ACETIC ACID for BROWN.

80 gallons Pyroligneous Acid10 lbs. Prussiate of Potash, yellow5 lbs. White Sugar of Lead.Boil 5 minutes, and let settle.

No. 133.

IRON MORDANT NEW.

24 gallons Iron Liquor 24° Twaddle
12 " Pyroligneous Acid 6° Twaddle
4 lbs. White Sugar of Lead
4 " Red Prussiate of Potash

4 " Nitrate of Potash

1 lb. Saltpetre.

Boil one hour, and let settle over night.

No. 134.

LIGHT RESIST RED.

8 gallons Water

2 " Red Liquor 16° Twaddle

20 lbs. Flour boiled

3 lbs. 12 oz. Muriate of Tin Crystals. Mix and strain.

No. 135.

MORDANT for BLACKS.

76 lbs. Acetate of Lime. Dissolve

28 " Copperas

66 " Alum

32 gallons Water.

Filter the clear liquor off.

No. 136.

BLACK PADDING LIQUOR.

18 gallons Red Liquor 16° Twaddle

18 " Mordant above

4 · " Pyroligneous Acid 6° Twaddle

40 "Water.

Stir up well.

No. 137.

IMPRESSION BLUE.

3 gallons Finishing Blue3 lbs. Crystal. Starch.Boil and strain.

DEN BEQU

No. 138.

5 V. BLACK.

3 gallons Common Iron 24° Twaddle
6 "Water

18 lbs. Flour.
Boil and strain.

No. 139.

2 A. BROWN.

4 quarts Acetate of Copper 16° Twaddle
4 gallons Gum Brown Standard
1 gallon Gum Water.
Mix and strain.

No. 140.

41 PASTE BROWN.

8 gallons Sal Ammoniac Standard 1 gallon Acetic Acid 6° Twaddle 1 " Water

1 water

14 lbs. New Flour

11 lb. Sal Ammoniac.

Boil and add

1 gallon Acetate of Copper 16° Twaddle. Mix and strain.

No. 141.

1 C. BROWN.

7 gallons Gum Brown Standard
1 gallon X Standard
1 " Acetate of Copper 16° Twaddle. Mix well, and strain.

No. 142.

32 P. BROWN.

 gallon Wood Acid 8° Twaddle
 "Water
 lbs. New Flour. Boil and add
 gallon Acetate of Copper 16° Twaddle. Mix and strain.

6 gallons Sal Ammoniac Standard

No. 143.

FINISHING BLUE.

18 gallons Water

21 lbs. Yellow Prussiate.

Dissolve in 14 gallons Hot Water

28 lbs. Copperas. Dissolve. Mix

2 gallons Water. Add

½ gallon Oxymuriate of Tin 120° Twaddle

6 gallons Hot Water. Dissolve

6 lbs. best Chrome. Mix

 $1\frac{1}{2}$ lb. Oxalic Acid. Dissolve in

2 gallons Hot Water, and

16 " Cold Water. Stir well.

No. 144.

W. BLACK WOOLLEN.

3 gallow Logwood 8° Twaddle

4 lbs. Starch, boiled

3 oz. Yellow Prussiate, cooled

4 gills Nitrate of Iron 80° Twaddle

2 " Muriate of Iron 60° Twaddle

2 " Nitrate of Copper. Mix well, and strain. No. 145.

P. BLACKS.

gallon Iron Liquor 24° Twaddle
 gallons Pyroligneous Acid 6° Twaddle
 " Water.
 Strain.

No. 146. TWICE D. Y. BROWN.

6 gallons Gum Brown Standard1 gallon Acetate of Copper 16° Twaddle.Mix and strain.

No. 147.

4 X BLACK.

3 gallons Water
1 gallon Wood Acid
1 " Iron Liquor 24° Twaddle
10 lbs. Flour.
Boil and strain.

No. 148.

PURPLE MORDANT.

5 gallons Water

5 " Wood Acid 6° Twaddle P. A.

2 " Iron Liquor 24° "

 $3\frac{3}{4}$ lbs. Copperas

1½ lb. Saltpetre

 $2\frac{1}{4}$ lbs. White Arsenic.

Boil 15 minutes, and let stand one night.

No. 149.

15 S. PURPLE ELIZERINE.

14 gallons Substitute Water
1 gallon Fixing Liquor 42° Twaddle
1 " X Purple Mordant.
Stir well and strain.

No. 150.

* 2 R. DRAB TWICE.

MADDER.

9 quarts Sal Ammoniae Standard

2 " Muriate of Iron 20° Twaddle

2 "Copper Acetate 16° "

1 quart Red Liquor 16° Twaddle

10 quarts Gum Water.

Mix and strain.

No. 151.

* 5 R. DRAB TWICE.

MADDER.

4 gallons Sal Ammoniac Standard
1 gallon Red Liquor 16° Twaddle
1 " Iron Liquor 24° "
1 " Acetate of Copper 16° Twaddle
7 gallons Gum Water Substitute.
Mix and strain.

No. 152.

* 11 RESIST RED TWICE.

24 lbs. Flour
12 gallons Red Liquor 16° Twaddle
½ gallon Japan Liquor 8° "
Boil well and add
10 lbs. Muriate of Tin Crystals.
Mix and strain.

No. 153.

* 4 M. DRAB TWICE.

3 measures Sal Ammoniac standard

24 " Gum Water

1 measure Sumach Liquor 10° Twaddle

1 "Lavender standard

1 "Iron Liquor 24° Twaddle

2 measures Acetate of Copper 16° Twaddle. Mix and strain.

No. 154.

X OXIDE OF CHROME STANDARD.

10 quarts Water. Dissolve in it

10 lbs. best Chrome. Then take

7½ "Sulphuric Acid 170° Twaddle.

Add 2 quarts of Cold Water. Mix. Add by degrees to the above. Then add

 $2\frac{1}{2}$ lbs. Common Sugar by degrees.

Let it stand until cool, and add 1 pint Muriate of Tin 120° Twaddle.

Mix, and measure all together.

There should be 3 gallons ready.

No. 155.

* 1 X SHADE.

4 quarts of the above Liquor-3 "Substitute Water. Mix and strain.

50249

No. 156.

OXIDE OF CHROME STANDARD.

8 lbs. best Chrome

2 gallons Water. Dissolve and add

1 quart Sulphuric Acid 166° Twaddle. Add

2 quarts Water. And add by degrees

2 lbs. Brown Sugar
Set, put in a pan, and boil down to 2 gallons.

No. 157.

2 SHADE.

2 gallons of the above

1 gallon Gall Liquor 18° Twaddle

1 " Iron Liquor 24° Twaddle

4 gallons Substitute Water.

Mix and strain.

No. 158. * 3 BLACK.

MADDER.

1 gallon Water

1 "P. A. Liquor 6° Twaddle

1 " Iron Liquor 24°

12 lbs. Flour.

Boil and strain.

No. 159.

* NEW CHOCOLATE.

2 gallons Red Liquor 6° Twaddle 1 gallon Iron Liquor 8° " 16 lbs. Flour.

Boil, mix, and strain.

No. 160.

PENCIL BLUE STANDARD.

1½ gallon Water

 $1\frac{1}{2}$ " 4 lb. Indigo

1 "Caustic Soda 70° Twaddle

43 lbs. Red Arsenic.

Boil 1 hour and add

1 lb. Dust Lime, and let stand all night, and strain, and add

8 lbs. Ground Gum Arabic, and strain again.

No. 161.

P. SLATE.

MADDER.

3 gallons of the above

3 "Gum Dragon Water 4 oz. per gallon

3 gallon Red Liquor 16° Twaddle. Mix and strain.

No. 162.

* 21 SLATE.

GARANCINE.

1 gallon fast Blue Standard

2 gallons Substitute Water

1 gallon Water

3 noggin Iron Liquor 24° Twaddle.

No. 163.

* OIL for COLORS TWICE.

1 gallon Galipoli Oil

1 " Palm Oil

1 lb. Flour. Dissolve; when half cooled add

1 quart Turpentine.

Mix well.

No. 164.

* 8 FAWN.

MADDER.

6 measures Sal Ammoniac Standard

2 "Oxide of Chrome

1 measure Iron Liquor 24° Twaddle

2 measures Acetate of Copper 16° Twaddle

12 "Substitute Water.

Mix and strain.

No. 165.

* 2 C. BROWN.

MADDER.

4 gallons X standard. Thicken with

6 lbs. 3 oz. Gum Substitute.

Heat to 180° and add 4 gallons Gum Brown

1 gallon Acetate of Copper 16° Twaddle.

Mix and strain.

No. 166.

* 8 NEW CHOCOLATE.

MADDER.

6½ gallons Water

1½ gallon Fixing Liquor 42° Twaddle

8 gallons Red Liquor 16° Twaddle

2 " Iron Liquor 24° "

32 lbs. new Flour.

Boil and strain.

No. 167.

* 15 NEW CHOCOLATE.

MADDER.

6 gallons Water

1½ gallon Fixing Liquor 42° Twaddle

7½ gallons Red Liquor 16° Twaddle

1 gallon Iron Liquor 24° Twaddle

30 lbs. new Flour.

Boil and strain.

No. 168.

BERRY LIQUOR AT 18° TWADDLE.

100 lbs. Berries with

18 gallons Bark Liquor 8° Twaddle.

It produces

22 gallons of Liquor 18° Twaddle.

No. 169.

6 FAWN.

GARANCINE.

3 gallons Oxide Chrome Standard

2 " Sal Ammoniac Standard.

8 "Substitute Water

1 gallon Iron Liquor 24° Twaddle

1 " Acetate of Copper 16° Twaddle.
Mix.

No. 170.

P. ALUMINATE OF SODA.

Take a large tub that will hold 200 gallons, and put in it 20 gallons Cold Water, 40 lbs. Alum dissolved in 20 gallons Hot Water; add to the above; and then take a pan, and put in it 3 gallons Caustic Soda 70° Twaddle, and add 6 gallons Water, and add to the above, and stir well, and wash three times with Cold Water, and filter to a pulp. Put in a pan, and add 2\frac{3}{4} gallons Caustic Soda 70° Twaddle. Stir well, and boil down to 12 gallons of Liquor, and filter through calico, and thicken with 20 lbs. 3 Gum Substitute heated 180°; heat and strain.

No. 171.

X STANDARD.

Put in a tub 20 gallons Cold Water; and add 40 lbs. Alum. Dissolve in 20 gallons Hot Water, and 38 lbs. Common Soda. Dissolve in 20 gallons Hot Water, stir well, and wash three times over. Filter, and put in a pan, and add $2\frac{1}{2}$ gallons Muriatic Acid 36° Twaddle, and boil down to 10 gallons of liquor. Should stand 10° Twaddle, and run through Calico.

No. 172.

SUBSTITUTE FOR A. RED

is 4 lbs. Brown British Gum per gallon.

Take 28 gallons of Boiling Hot Water, and beat up 112 lbs. of the above gum, and strain.

No. 173.

2 A. RED

is 2 Substitute, and 1 of Red Liquor 16° Twaddle.

No. 174.

3 A. RED

is 3 Substitute, and 1 of Red Liquor 16° Twaddle.

No. 175.

4 A. RED

is 4 Substitute, and 1 of Red Liquor 16° Twaddle.

No. 176.

5	A.	Red.	10	A.	RED.
6	A.	Red.	12	A.	RED.
7	A.	Red.	16	A.	Red.
8	A.	RED.	2	Α.	REDS

9 A. Red.

These are all the shades, and use 1 gill of Acetic Acid for every gallon of color.

No. 177.

15 FAWN.

GARANCINE.

2gallons Gall Liquor $18\,^{\circ}$ Twaddle

2 " Sal Ammoniac Standard

13 gallons Substitute Water

1 gallon Iron Liquor 24° Twaddle

1 " Acetate of Copper 16° Twaddle.
Mix and strain.

No. 178.

4 X SHADE.

1 gallon Oxide of Chrome Standard4 gallons Subte. Water.Mix and strain.

No. 179.

3 X SHADE.

1 gallon Oxide of Chrome Standard3 gallons Substitute Water.Mix and strain.

No. 180.

17 STONE.

GARANCINE.

6 gallons Sal Ammoniac Standard 20 "Substitute Water

Substitute water

1 gallon Muriate of Iron 20° Twaddle

2 gallons Acetate of Copper 16° Twaddle. Mix and strain.

No. 181.

ULTRAMARINE BLUE.

STEAM.

24 lbs. Blue 24 " Albumen Water. Mix dry.

No. 182.

2½ gallons Water at 140° F.

4 quarts Glue at 4 lbs. to a gallon

1 quart Turpentine.

4 quarts Acetate of Soda. Mix and stir 1 hour.

1 pint Spirits of Wine. Stand all night.

1 gill Oil.

Mix and strain.

No. 183.

1 gallon Water

4 lbs. Acetate of Soda

4 oz. White Arsenic.
Dissolve and add

1 gallon Hot Water

2 lbs. Alum.

Dissolve. Mix by degrees to the above.

No. 184.

FAST GREEN.

STEAM.

8 quarts Blue Standard
3 "Acetate of Tin

2½ " Nitrate of Lead.

Mix and strain.

No. 185.

X STANDARD FOR NITRATE OF LEAD.

In 1 quart Water dissolve
2½ lbs. Nitrate of Lead, and add
1 quart Gum Water.
Mix.

No. 186.

NITRATE OF IRON PULP.

3 gallons Nitric Acid 64° Twaddle 1 gallon Hot Water.

Dissolve in your Iron till it will take no more.

No. 187.

WOLLIN WALKER BLACK.

3 gallons Logwood Liquor 8° Twaddle

3 lbs. Gum Starch

12 oz. Blue Stone (Sulphate of Copper)

12 oz. Copperas (Sulphate of Iron).

Boil, and let it be half cooled, and add

2 quarts Nitrate of Iron Pulp.

No. 188.

4 B. DRAB STEAM X.

12 lbs. Albumen

1 lb. Lampblack. Mix dry.

3 gallons Water.

Beat up, stir 1 hour, stand 1 night; strain.

No. 189.

X DARK C. BUFF STANDARD.

10 quarts Bark Liquor 12° Twaddle.

4 " Sapan Extract

1 lb. Alum

4 oz. Chloride of Potash.

Dissolve.

No. 190.

X 1 STEAM BROWN.

4 quarts of above Standard
10 lbs. 3 Gum Substitute
1 oz. Chloride of Potash.
Heat 180° F., and add
1 quart Red Liquor 16° Twaddle

1 quart Red Liquor 16° Twaddle 1½ " D. Purple Standard.

No. 191.

X. ORANGE.

6 gallons Bark Liquor 12° Twaddle

2 "Sapan Extract.

12 lbs. Gum Starch.

 $1\frac{1}{2}$ " Alum. Boil and add

 $1\frac{1}{2}$ " Tin Crystals.

1 quart Red Liquor 16° Twaddle. Mix and strain.

No. 192. LIGHT BROWN.

STEAM.

5 quarts Bark Liquor 12° Twaddle

5 "Berry Liquor 12° Twaddle

12 oz. Cream of Tartar

1 oz. Chloride of Potash

7 lbs. 3 Gum Substitute

2 oz. Red Prussiate of Potash. Dissolve

2-quarts Sapan Extract

1½ pint D. Purple Standard

1½ " Sapan Liquor at 8° Twaddle.Mix and strain.

No. 193.

X DARK PURPLE STANDARD.

1 gallon Hot Water

10 oz. Alum

10 " Red Prussiate of Potash.

Dissolve; put in

1 gallon Logwood Liquor 8° Twaddle

1 quart Sapan Liquor 8° Twaddle.

No. 194.

DARK BROWN.

STEAM.

4 gallons Bark Liquor 20° Twaddle

3 lbs. Alum

7." Gum Starch. Boil and add

4 oz. Chloride of Potash

4 " Red Prussiate

1 gallon Sapan Extract

3 quarts D. Purple Standard. Strain.

No. 195.

X 1 P. DRAB.

STEAM.

2 gallons C. Buff Standard

1 gallon at 4 lbs. Lavender

1 gallon Gall Liquor 18° Twaddle

1 noggin Iron Liquor 24° '

4 gallons Substitute Water. Mix and steam.

7

No. 196.

X PAD BLUE.

STEAM.

4 gallons Cold Water

10 lbs. Starch

3 lbs. Sal Ammoniac. Boil and add

15 " Tartaric Acid

4 gallons Tin Pulp

1 lb. Oxalic Acid. Dissolve in

1 quart Water

13 lbs. Yellow Prussiate of Potash

3 lbs. Red Prussiate of Potash. Mix and strain.

> No. 197. X STEAM.

> > BLACK.

8 gallons Logwood 8° Twaddle

1 gallon Acetic Acid 8° Twaddle

2 gallons Iron Liquor 24° Twaddle

15 lbs. Starch.

Boil and strain.

No. 198.

X A. CHOCOLATE.

STEAM.

 $7\frac{1}{2}$ gallons Sapan Extract

5½ " Logwood Standard

2 " Lavender at 4 lb. per gallon.

1 gallon Bark Liquor 8° Twaddle

24 lbs. Gum Starch

3 " Alum

1 lb. Yellow Prussiate.

Boil and strain.

No. 199.

SPIRIT BLACK.

STEAM.

8 quarts Logwood 8° Twaddle

4 " Iron Liquor 24° Twaddle

2 " Vinegar 4° Twaddle

2 " Red Liquor 16° Twaddle

16 lbs. Gum Starch.

Boil and strain.

No. 200.

X DARK BLUE.

STEAM.

6 gallons Water

20 lbs. Starch. Boil and add

3½ " Sal Ammoniac

20 " Tartaric Acid

1 lb. Oxalic Acid. Dissolve in

1 quart Water.

5 gallons Pulp Tin

20 lbs. Yellow Prussiate of Potash

2 " Red Prussiate of Potash. Mix and strain.

No. 201.

X DARK C. DRAB.

STEAM.

9 gallons Gall Liquor 18° Twaddle

3 " Lavender at 4 lbs.

1 gallon common Iron Liquor 24° Twaddle

30 lbs. 3 Gum Substitute.

Heat to 180° F. Strain.

No. 202.

X GALL STANDARD.

CALICO.

9 quarts Gall Liquor 18° Twaddle
1 quart Logwood 8° Twaddle
1 "Nitrate of Iron 80° Twaddle.
Mix and let settle.

No. 203.

X DARK PASTE.

OLIVE.

6 quarts Berry Liquor 8° Twaddle
2 "Red Liquor 16° Twaddle
2 "Gall Standard
2½ lbs. Starch.
Boil and strain.

No. 204.

X 6 PASTE.

OLIVE.

6 quarts Berry Liquor 8° Twaddle
2 "Red Liquor 16° Twaddle
2 "Gall Standard
4 "Water
3½ lbs. Crystal Starch
Boil and strain.

7*

No. 205.

X 6 DARK GREEN.

9 gallons Bark 12° Twaddle

13 lbs. Gum Starch

5 " Alum. Boil and add

1 pint Muriate of Tin 120° Twaddle

6 lbs. Tartaric Acid

1 lb. Oxalic Acid. Dissolve

15 lbs. Yellow Prussiate.

Mix and strain.

No. 206.

X PEA-GREEN or 16 GREEN.

STEAM.

13 gallons Berry Liquor 18° Twaddle

16 lbs. Ground Alum

1 gallon Acetic Acid 8° Twaddle

½ gallon Muriate of Tin 120° Twaddle.

Dissolve 32 lbs. Yellow Prussiate of Potash in

13 gallons Gum Substitute Water.
Mix and strain.

No. 207.

X LIGHT GREEN.

STEAM.

5 gallons Berry Liquor 18° Twaddle

1 gallon Hot Water

8 lbs. Ground Alum

1 quart Muriate of Tin 120° Twaddle

3 quarts Vinegar.

Mix and add

11 lbs. Yellow Prussiate of Potash

10½ gallons Gum Water.

Mix and strain.

No. 208.

X 16 DARK C. BLUE.

1 gallon Water

5 lbs. Starch.

1 gallon Iron Liquor 24° Twaddle

2 gallons China Blue Standard. Mix, boil well, and strain.

No. 209.

X 16 GUM BLUE.

CHINA RIGHT.

4 gallons Standard Blue

2 "Gum Water

2 " common Iron Liquor 24° Twaddle. Mix well and strain.

No. 210.

X 4 GUM C BLUE.

2 gallons 8 Blue China
1 gallon Gum Water
1 "Iron Liquor 24° Twaddle.
Mix well and strain.

No. 211.

PRUSSIATE TIN PULP.

Take a large tub, and put in—
10 gallons Hot Water, in which you dissolve
16 lbs. Yellow Prussiate Potash.

Take-

8 gallons Cold Water, to which you add

2 " Muriate of Tin 120° Twaddle.

Add the Tin to the Prussiate; mix well; wash three times over; filter.

No. 212.

X DARK FAST GREEN.

6 quarts Blue Standard

2 " Acetate of Tin

2 " Nitrate of Lead. Mix and strain.

No. 213. DARK FAST BLUE.

4 gallons Standard Blue1 gallon Acetate of Tin.Mix and strain.

No. 214. No. 1. FAST BLUE.

2 gallons Standard Blue1 gallon Acetate of Tin1 gallon Gum Water.Mix and strain.

No. 215.

No. 2. FAST BLUE

1 gallon Blue Standard
2½ quarts Acetate of Tin
5 "Gum Water.
Mix and strain.

No. 216.

No. 3. FAST BLUE.

2 gallons Blue Standard
1½ gallon Acetate of Tin
4½ gallons Gum Water.
Mix and strain.

No. 217.

· No. 4. FAST BLUE.

2 gallons Blue Standard
13/4 gallon Acetate of Tin
61/4 gallons Gum Water.
Mix and strain.

No. 218.

No. 6. FAST BLUE.

gallon Blue Standard
 " Acetate of Tin
 gallons Gum Water.
 Mix and strain.

No. 219.

12 C. BLUE.

2 gallons Blue Standard
1½ gallon common Iron Liquor 24° Twaddle
1½ " Water
6 lbs. Starch.
Boil well and strain.

No. 220.

8 GUM BLUE.

CHINA.

2 gallons Blue Standard

3 "Gum Water

3 " common Iron Liquor 24° Twaddle. Mix well and strain.

No. 221.

SCARLET RED.

WOOLLEN NOT SO GOOD.

3 quarts Sapan Liquor 12° Twaddle

1 quart Bark Liquor 12° Twaddle

1 lb. of Gum Starch, boil; half cool, add

1 gill Nitrate of Iron 80° Twaddle

1 " Oxymuriate of Tin

4 lbs. Pink Salts. Strain.

No. 222.

GREEN FOR WOOLLEN.

1 gallon Bark Liquor 22° Twaddle

1 lb. Gum Starch

3 lbs. Alum, boil; half cool, add

2 " Muriate of Tin Crystals

2 " Yellow Prussiate. Mix

1 pint Extract of Indigo. Strain.

No. 223.

ACETATE OF TIN.

6 quarts Water 32 lbs. White Sugar of Lead.

Dissolve in the Boiling Water; then take a half piece mug; put in 2 gallons Muriate of Tin 120° Twaddle; mix both well together; then put in 1 gallon of Water more; mix all up together. When filtered, should be 4 gallons. Should stand 30° Twaddle. Dissolve in that 10 lbs. Gum Senegal ground. Strain.

No. 224.

STEAM ORANGE FOR WOOLLEN.

1 quart Sapan Liquor 8° Twaddle.

3 pints Bark Liquor 22° Twaddle

3 " Bark Liquor 12° Twaddle

20 oz. Starch. Boil, half cool, and add

3 gills Oxymuriate of Tin 120° Twaddle. Mix and strain.

No. 225.

STANDARD CHINA BLUE.

27 gallons Iron Liquor 24° Twaddle 54 lbs. Copperas. Dissolve

90 lbs. Indigo, and grind in the mill 14 days.

Wash the mill out with 4 gallons Water, and then measure all together 45 gallons of Pulp.

No. 226.

RED FOR WOOLLEN.

2½ quarts Sapan Liquor 8° Twaddle

1 quart Extract

1 pint Bark Liquor 22° Twaddle

1 lb. Gum Starch, boil, let half cool

1 gill Nitrate of Iron 80° Twaddle

1 pint Oxymuriate of Tin 120° Twaddle

1 noggin Muriate of Tin 120° Twaddle. Strain.

No. 227.

STANDARD FOR PAD NEW BLUE.

6 gallons Hot Water

12 lbs. Tartaric Acid. Dissolve

12 " Yellow Prussiate.

Let settle; take clear liquor for use.

No. 228.

D. 4 P. BLUE FOR BLACK SHADE WOOLLEN.

STEAM.

4 gallons of the above Steam

12 lbs. Crystal Starch. Boil and add

4 gallons Tin Pulp

6 lbs. Tartaric Acid

4 " Sal Ammoniac

1 quart Water

1 lb. Oxalic Acid. Dissolve

10 lbs. Yellow Prussiate.

Stir well; strain on Calico cloth.

No. 229.

DARK BUFF PASTE 6 & 3 STANDARD.

STEAM.

3 gallons Buff Liquor

6 lbs. Gum Starch.
Boil and strain.

No. 230.

1 BUFF PASTE.

STEAM.

2 gallons Buff Liquor 6 and 3 Standard

2 gallons Water

8 lbs. Flour.

Boil and strain.

No. 231.

2 BUFF PASTE.

2 gallons Buff 6 and 3 Standard
4 "Water.
Thicken with 12 lbs. Flour.
Boil and strain.

No. 232.

* 6 and 3 BUFF STANDARD.

20 gallons Hot Water
240 lbs. Sulphuret of Iron. Dissolve
120 lbs. Brown Sugar of Lead.
Dissolve in 20 gallons of water.
Mix together, and let settle.

No. 233.

* 1 FAST BUFF.

1 gallon of the above Liquor1 "Substitute Water.Mix well and strain.

No. 234.

* 2 FAST BUFF.

2 gallons Buff Standard

4 "Substitute Water.

Mix well and strain.

* Reduce the others according to number.

No. 235.

* 4 LB. INDIGO.

IN THE MILL.

16 gallons Water.

80 lbs. Indigo, ground well.

Measure to 20 gallons pulp when out of the mill.

No. 236.

4 B. DRAB.

STEAM.

3 gallons Warm Water 150° F.

6 oz. Strong Liquor Ammonia

3 lbs. Proteine Gum

1 noggin Oil

½ oz. Ultramarine Blue

12 oz. Lampblack.

Mix dry and add to the above

1 gill turpentine.

Put in a water-bath until it has become thin.

No. 237.

* No. 1 BLUE.

VAT.

Take 120 gallon tub; half fill it with Water, and add to it 10 gallons Hot Water. Dissolve in it

30 lbs. Copperas

3 gallons Ground Pulp

4 lbs. Indigo.

Mix well, and add

30 lbs. Slack Lime

Stir well up, and let stand for three to four weeks, when it will be ready for use.

No. 238.

No. 2 BLUE VAT.

120 gallons Water

1 gallon Indigo at 4 lbs.

10 gallons Hot Water. Dissolve

15 lbs. Copperas, and add

15 " Lime.

Stir well, and let stand three or four weeks, when it will be ready for use.

No. 239.

No. 3 BLUE VAT.

120 gallons Water
10 " Hot Water
5 lbs. Dissolved Copperas.
Stir well and let stand four weeks.

No. 240.

No. 4 BLUE VAT.

120 gallons Water10 " Hot Water3 lbs. Dissolved Copperas.Stir well, and let stand four weeks.

No. 241.

TO PRECIPITATE PULP.

40 gallons No. 1 Vat
½ gallon Muriate of Tin 120° Twaddle.
Mix and filter.

No. 242.

40 gallons No. 2 Vat ½ gallon Muriate of Tin 120° Twaddle.
Mix well.

No. 243.

40 gallons No. 3 Vat
¹/₂ gallon Muriate of Tin 120° Twaddle.
Mix well and filter.

You should get about 80 gallons of clear liquor of the tubs, and this you will find to run to about 1 to 8 of Tin 120° Twaddle. Filter to a pulp; you will get about 8 gallons of pulp of 3 tubs. Thicken with 16 lbs. of ground Gum Senegal.

This is for Fast Blues.

No. 244.

1 C. BLACK FOR ORANGES.

4 gallons Logwood 8° Twaddle. Thicken with 2 lbs. Flour.

4 oz. Bichromate of Potash.

Dissolve in 1 quart of Hot Water 2 lbs. Starch.

Boil \(\frac{3}{4} \) noggin Nitrate of Iron 80° Twaddle in

1 pint Oil.

Mix and strain, and put in this 1 gill Oxymuriate of Tin 120° Twaddle.

No. 245.

ULTRAMARINE BLUE, LIGHT.

5 lbs. new Gum Albumen

3 " Ultramarine Blue. Mix dry.

10 quarts Cold Water

1 quart Caustic Soda 10° Twaddle.

Put in a water-bath heated to 160° F.; stir 1 hour, let stand all night.

1 gill Turpentine.

Strain.

No. 246.

LIGHT PINK, WOOLLEN.

7 pints Sapan Liquor 8° Twaddle

1 pint Extract of Sapan

4 oz. Blue Stone

1½ lb. Gum Starch, boil, and when half cold add
½ noggin Nitrate of Iron.

Set 3 gills Oxymuriate of Tin 120° Twaddle

, 1 gill Muriate of Iron.

Mix and strain.

No. 247.

X 6 LIGHT C. BLUE.

2 gallons of Blue 8 C. Blue
½ gallon Gum Water
½ " Iron Liquor 24° Twaddle
Mix well and strain.

No. 248.

OXIDE OF TIN.

FOR MADDER PULP ORANGES.

In 2 gallons Hot Water, dissolve
6 lbs. Muriate of Tin Crystals.
In 2 gallons Hot Water, dissolve
6½ lbs. Common Soda.

Add your Soda to the Tin; stir well, and wash three times over with cold Water, and through a calico to a pulp.

No. 249.

* 1 X BLUE.

4 gallons of Cold Water6 lbs. Crystal Starch. Boil and add4 gallons D. X Blue.Mix and strain.

No. 250.

4 LB. LAVENDER.

160 lbs. Logwood ground wet40 gallons best Red Liquor 16° Twaddle.

Warm. Let steep for three or four days, when it is ready for drawing off.

No. 251.

RED LIQUOR.

4 gallons Hot Water 16 lbs. Ground Alum

19 " White Sugar of Lead.

Dissolve, and add by degrees half a gallon of the above Water; mix

1 lb. Ground Chalk.

Mix and let settle.

No. 252.

* DARK PASTE ORANGE.

120 lbs. Brown Sugar of Lead16 gallons Water.

Dissolve and filter; use the clear Liquor.

4 gallons Water, cold

20 lbs. Crystal Starch.

Boil and strain.

No. 253.

* 1 PASTE ORANGE.

20 lbs. Brown Sugar of Lead

16 gallons Water.

Dissolve and filter, and use the clear Liquor.

4 gallons Cold Water

20 lbs. Crystal Starch.

Boil and strain.

No. 254.

9 DARK ORANGE.

36 lbs. Brown Sugar of Lead.

Dissolve in 21 gallons of Water, and filter.

4 lbs. Starch

1 gallon Cold Water.

Boil and strain.

No. 255.

* 2 PASTE ORANGE.

40 lbs. Brown Sugar of Lead

16 gallons Water.

Dissolve and filter, and use the clear Liquor.

4 gallons Cold Water

20 lbs. Starch Crystals.

Add the above and boil.

No. 256.

* 4 PASTE ORANGE.

40 lbs. Brown Sugar of Lead

8 gallons Water.

Dissolve and filter, and use the clear Liquor.

2 gallons Cold Water

10 lbs. Crystal Starch.

Add the above Liquor; and boil and strain.

No. 257.

8 LIGHT ORANGE.

8 lbs. X Brown Sugar of Lead

12 gallons Water.

Dissolve and filter the clear Liquor.

16 lbs. Crystal Starch

4 gallons Cold Water.

Boil and strain.

No. 258.

12 LIGHT ORANGE.

12 lbs. Brown Sugar of Lead

12 gallons Water.

Dissolve and filter the clear Liquor.

16 lbs. Starch Crystals.

Add the above Liquor; boil and strain.

4 gallons Cold Water to Starch.

No. 259.

* G. ORANGE or 4 MADDER ORANGE.

4 gallons Bark Liquor 16° Twaddle

6 lbs. Gum Starch

4 " Sal Ammoniac

1 quart Aluminate of Soda X Standard. Boil; when half cold add

8 lbs. Muriate of Tin Crystals. Mix and strain.

No. 260.

* 4 S. ORANGE.

20 lbs. Brown Sugar of Lead; dissolve it in $2\frac{1}{2}$ gallons Hot Water.

Filter off and add

2½ gallons Gum Water.
Mix well and strain.

No. 261.

4 7 SHADE.

1 gallon Oxide Standard

3 gallons, 6 and 3 Buff Standard

2 "Gum Substitute at 10 lbs. per gallon; add

1 gill Logwood Liquor 8° Twaddle

1 "Gum Brown Standard.
Mix well and strain.

No. 262.

* 2 MADDER ORANGE.

4 gallons Bark Liquor 16° Twaddle

4 lbs. Gum Starch

2 " Sal ammoniae, boil, add

2 qts. X Standard

1 qt. Oxide of Tin Pulp

6 lbs. Muriate of Tin Crystals. Mix well and strain.

No. 263.

* 1 P. GREEN.

1½ gallon Oxide Standard
½ " Light Steam Green
2 gallons Gum Sub. Water.
Mix and strain.

No. 264.

16 G. C. BLUE.

2 gallons Iron Liquor 24° Twaddle

2 " Gum Water

2 "Standard Blue Pulp. Mix and strain.

No. 265.

* ANNOTTO ORANGE STANDARD.

4 gallons Caustic Soda 14° Twaddle.

8 lbs. Annotto; add

2 gallons Water. Boil two hours.

To 14 qts. Liquor, add 2 qts. of X Standard by degrees, and filter.

No. 266.

* 4 S. ORANGE STEAM.

1 gallon of the above Standard

4 gallons Substitute Water. Stir well and strain.

No. 267.

4 PASTE BLUE.

7 gallons Water, cold

8 lbs. Crystal Starch, boil

8 oz. Oxalic Acid. Dissolve, and add

1 gallon Blue Pulp

2 gallons Pad Blue Standard. Mix and strain. No. 268.

* 8 PASTE BLUE.

7 gallons Cold Water
8 lbs. Crystal Starch; boil
8 oz. Oxalic Acid; dissolve
1 gallon Blue Pulp
1 pad Blue Standard.
Mix and strain.

No. 269.

10 PASTE BLUE.

9 gallons Cold Water
10 lbs. Crystal Starch; boil
10 oz. Oxalic Acid. Dissolve, and add
1 gallon Blue Pulp
1 "Pad Blue Standard.

No. 270.

* 2 LIGHT BLUE.

gallon Blue Pulp
 gallons 4 P Blue Standard
 oz. Oxalic Acid. Dissolve in
 qt. Hot Water
 gallons Soluble Substitute Water.
 Mix well up and strain.

No. 271.

* 3 LIGHT BLUE.

2 gallons Blue Pulp
5 " Pad Blue Standard
1½ lb. Oxalic Acid. Dissolve in
3 qts. Hot Water
13 gallons Soluble Substitute Water.
Mix and strain.

No. 272.

* 5 LIGHT BLUE.

2 gallons Blue Pulp.
3 " Pad Blue Standard
1½ lb. Oxalic Acid. Dissolve in
3 qts. Hot Water.
14 gallons Soluble Substitute Water.
Mix and strain.

No. 273.

* 8 LIGHT BLUE.

gallon Blue Pulp
 oz. Oxalic Acid. Dissolve in
 qt. Hot Water
 gallon Pad Blue Standard
 gallons Soluble Substitute Water.
 Mix and strain.

No. 274.

S. N. YELLOW.

ROYAL.

2 gallons Berry Liquor 12° Twaddle.

2 "Bark Liquor 8° Twaddle

5 lbs. Starch. Boil, and add

1 qt. Oxide Tin Pulp; add

2 qts. best red Liquor 18° Twaddle. Mix well, and add

6 oz. Muriate of Tin Crystals, and strain.

No. 275.

X 1½ B. PURPLE PASTE.

ROYAL.

2 gallons B Purple, and

3 "Water

5 lbs. New Flour. Boil and strain.

No. 276.

1 NEW BROWN STEAM.

8 qts. Bark Liquor 20° Twaddle

6 lbs. 3 Gum Substitute

18 oz. Alum

2 " Chloride of Potash.

Half boil, and add

2 qts. 4 lbs. Lavender Standard

2 " Sapan Extract

1 qt. Acetate of Tin 6° Twaddle. Mix, and strain.

No. 277.

ACETATE TIN.

7 pints Water; dissolve in 1 pint Muriate of Tin 120° Twaddle 2 lbs. White Sugar of Lead.

Mix, let settle, and use the clear liquor.

No. 278.

R. PURPLE STANDARD.

STEAM.

2 qts. Logwood 8° Twaddle

2 oz. Oxalic Acid

1 oz. Chloride Potash

4 oz. Yellow Prussiate Potash

4 " Red

" "

4 " Tartaric Acid. Dissolve and add 1 qt. 4 lbs. Lavender Standard

1 qt. Red Liquor 16° Twaddle

3 gills Cochineal Liquor 6° Twaddle.
Mix well.

No. 279.

3 PUCE STEAM.

1 gallon R. Purple Standard 3 gallons Substitute Water. Mix and strain.

No. 280.

8 PUCE STEAM.

8 gallons Substitute Water1 gallon R. Purple StandardMix and strain.

No. 281.

5 M. DRAB TWICE.

IN GARANCINE.

33 qts. Sal Ammoniac Standard
1 qt. Iron Liquor 24° Twaddle
1 " Sumac Liquor 10° Twaddle
1 " 4 lb. Lavender Standard
3 qts. Acetate Copper 16° Twaddle
30 " Gum Water

Mix and strain.

No. 282.

W. RED, STEAM.

4 qts. Sapan Liquor 8° Twaddle
1 qt. Bark Liquor 8° Twaddle
2 qts. Water
1 qt. X Standard
2 oz. Chloride Potash
2½ lbs. Starch.
Boil and strain.

No. 283.

DARK SPIRIT.

PINK WOOLLEN.

- 2 gallons Sapan Liquor 6° Twaddle
- 3 lbs. Starch. Boil, and add
- 2 noggins Nitrate of Iron 84° Twaddle
- 1 qt. Oxymuriate of Tin 120° Twaddle. Mix and strain.

No. 284. DARK SPIRIT.

PURPLE STANDARD.

6 oz. Sal Ammoniac; dissolve it in
6 qts. Logwood Liquor 8° Twaddle
1 noggin Nitrate of Iron 84° Twaddle
1 pint Oxymuriate of Tin 120° Twaddle.
Mix and strain.

No. 285.

W. R. ORANGE.

STEAM.

6 qts. Bark Liquor 8° Twaddle

1 qt. Sapan Extract

½ " X Standard

 $2\frac{1}{2}$ lbs. Starch. Boil, and add

1 oz. Chloride of Potash, When half cool, add

1 oz. Oxalic Acid

½ " Muriate of Tin Crystals. Mix and strain.

No. 286.

No. 2. B. CHOCOLATE.

STEAM.

10 qts. Sapan Extract

5 " 4 lbs. Lavender Standard

1 qt. Logwood Liquor 8° Twaddle

4 oz. Chloride of Potash

4 " Sal Ammoniac

6 lbs. Starch. Boil, and add

1 gallon Acetic Acid 8° Twaddle. Mix and strain.

No. 287.

2 W. ORANGE N.

3 qts. Berry Liquor 12° Twaddle

3 " Bark Liquor 8° Twaddle

3" Sapan 8° Twaddle

3 lbs. Starch

1 pint Red Liquor 16° Twaddle

2 oz. Chloride of Potash. Boil, and add

1 pint X Standard

2 pints Oxide of Tin Pulp

2 oz. Oxalic Acid. Stir well and strain.

No. 288.

W. MYRTLE GREEN.

STEAM.

4 gallons Bark Liquor 20° Twaddle

6 lbs. Starch

2 " Alum. Boil, and add

8 oz. Muriate of Tin Crystals

6 lbs. Super-Sulphate of Potash

8 " Yellow Prussiate of Potash

2 qts. Logwood Standard. Mix and strain.

10

No. 289.

W. CHOCOLATE.

STEAM.

3 gallons Logwood Standard.

1 gallon Bark Liquor 8° Twaddle

4 gallons Sapan Extract

12 lbs. Starch

1½ gallon Red Liquor 16° Twaddle

6 oz. Chloride of Potash.

Boil, and add

4 oz. Red Prussiate of Potash

6 "Yellow "

Mix and strain.

No. 290.

* 4 N. BROWN.

2 gallons of 2 M. Brown

2 "Substitute Water

3 gills Acetate of Tin 6° Twaddle

4 oz. Alum

¹/₄ oz. Chloride of Potash. Mix and strain.

No. 291.

* LIGHT ULTRAMARINE.

BLUE STEAM.

8 lbs. Albumen Gum, Ferguson

4 lbs. Ultramarine Blue

6 qts. Water 110° Fahr.

1 gill Turpentine

1 pint of Gum Water, 18 oz. per gallon

4 qts. Gum Dragon Water, 6 oz. per gallon. Let stand all night, and strain.

No. 292.

NEW ORANGE FOR ULTRAMARINE.

This is to work with Ultra.

 $2\frac{1}{4}$ lbs. Litharge and Blue

4 lbs. White Sugar of Lead

6 gallons Water. Boil down to 1 gallon and add

 $1\frac{1}{2}$ lb. Chrome.

Let stand two hours, and filter; wash three times over, and put in a pan, and add one half gallon Caustic Soda 8° Twaddle; let it stand one hour, take out, and wash three times over again, and filter.

No. 293.

S. C. NEW ORANGE.

3 qts. of the above1 quart Water1 lb. Starch.Boil well and strain.

No. 294.

* STEAM BROWN STANDARD.

24 lbs. Catechu. Boil and add
1½ lb. Sal Ammoniae
1½ "Pearlash. Dissolve.
Measure to 6 gallons, and filter.
12 lbs. 3 Gum Substitute heated to 180°.
Strain, and add
1 qt. Acetic Acid 8° Twaddle
½ "Nitrate of Copper 77° Twaddle.

No. 295.

$3\frac{1}{2}$ F. BROWN.

1 gallon Steam Brown Standard
3 gallons Substitute Water
½ gallon Water
¼ " Acetate of Copper 16° Twaddle.
Mix and strain.

No. 296.

D. S. BLUE NEW-BLUE ROYAL.

STEAM.

4 gallons Cold Water

12 lbs. Starch

4 " Sal Ammoniac. Boil, and add

4 gallons Blue Pulp

12 lbs. Super Sulphate of Potash

12 " Yellow Prussiate of Potash

4 " Red Mix and strain.

No. 297.

PLUM SHADE.

STEAM.

6 gallons Sapan Extract

2 " 2 L. Blue

1 gallon B. Purple Standard.

Thicken with Substitute; mix and strain.

10*

No. 298.

N. 3 YELLOW.

STEAM.

1 gallon Bark Liquor 8° Twaddle

1½ lb. Starch

3 oz. Alum

2 " White Sugar of Lead. Boil and add

3 oz. Muriate of Tin Crystals. Mix and strain.

No. 299.

2 PLUM SHADE.

STEAM.

6 gallons Sapan Extract

3 " 2 L. Blue

2 "B. Purple Standard

22 lbs. 3 Gum Substitute Water. Mix and strain.

No. 300.

3 W. ORANGE LAST.

STEAM.

1 gallon Berry Liquor 12° Twaddle

1 " Bark Liquor 8° Twaddle

1 "Sapan Liquor 8° Twaddle

4 lbs. Starch

9 oz. White Sugar of Lead.

1 qt. Standard. Boil, and add

6 oz. Muriate of Tin Crystals. Mix and strain.

No. 301.

C. STANDARD YELLOW.

- 2 gallons Bark Liquor 12° Twaddle
- 3 lbs. Starch ·
- 4 oz. White Sugar of Lead
- 1 qt. Red Liquor 16° Twaddle. Boil and add
- 6 oz. Muriate of Tin Crystals. Mix and strain.

No. 302.

* N. 16 GREEN.

STEAM.

13 gallons Berry Liquor 16° Twaddle

16 lbs. Alum

1 gallon Acetic Acid, brown

1/2 "Muriate of Tin 120° Twaddle

13 gallons Substitute Water.

No. 303.

7 DARK GREEN.

STEAM.

9 gallons Bark Liquor 12° Twaddle

12 lbs. Starch

- 21 " Alum. Boil and add

8 "Super Sulphate of Potash

9 oz. Muriate of Tin Crystals

14 lbs. Yellow Prussiate of Potash.

Mix and strain.

No. 304.

* S. BLUE.

STEAM.

4 gallons Cold Water

15 lbs. Starch

4 " Sal Ammoniac. Boil and add

8 "Super Sulphate of Potash

6 " Tartaric Acid

4 gallons Blue Pulp

4 oz. Oxalic Acid: dissolve in

1 pint Hot Water, and add

13 lbs. Yellow Prussiate of Potash

3 "Red " "
Mix and strain.

No. 305.

S. BLUE.

STEAM.

4 gallons Cold Water

14 lbs. Starch

3 " Sal Ammoniac, boil

6 " Tartaric Acid

6 "Super Sulphate of Potash

4 gallons Blue Pulp

8 oz. Oxalic Acid: dissolve in

1 pint Water.

13 lbs. Yellow Prussiate of Potash

3 " Red " "

Mix and strain.

No. 306.

BLACK FOR WOOLLEN.

3 gallons Logwood Liquor 8° Twaddle

5 lbs. New Flour

3 oz. Yellow Prussiate.

Boil. When half cold add

6 gills Nitrate of Iron 80° Twaddle

2 " Acetate Copper 16° Twaddle Mix and strain.

No. 307.

DARK ULTRAMARINE BLUE.

10 lbs. Ferguson Gum

12 " Ultramarine Blue. Mix.

6 qts. Water 100° Fahr.

2 " A. Soda

1 pint Turpentine

1 gallon 1 lb. Glue Water.

'Let steep all night. Strain.

No. 308.

8 T. PASTE.

1 gallon Water

1 lb. Starch. Boil and add

6 oz. Muriate of Tin Crystals.
Mix and strain.

No. 309.

* NEW FINISHING.

BLUE.

8 gallons Hot Water

8 lbs. Yellow Prussiate

2 qts. Nitrate of Iron 84° Twaddle

2 " Vitriol 166° Twaddle

2 " Red Orchil

Wash till all the acid is out, and add 6 oz. Oxalic acid.

No. 310.

PAD BLUE FOR PRINTING.

STEAM.

4 gallons Cold Water

14 lbs. Starch. Boil and add

3 " Sal Ammoniac

14 " Tartaric Acid. Dissolve in

4 gallons Blue Pulp

8 oz. Oxalic Acid. Dissolve

1 qt. Hot Water

14 lbs. Yellow Prussiate

2 " Red "

Mix and strain.

No. 311.

5 NEW CHOCOLATE.

STEAM.

4 gallons Bark Liquor 10° Twaddle

2 "Sapan Extract

1 gallon 4 lbs. Lavender

8 oz. Alum

2 " Chloride of Potash

12 lbs. Starch. Boil, and add

1 gallon P. Purple Standard. • Mix well and strain.

No. 312.

* * 12 CHINA LAST.

BLUE.

 $1\frac{1}{2}$ gallon Water.

1½ " Iron Liquor 24° Twaddle

2 gallons Pulp Standard

6 lbs. New Flour.

Boil. When half cold add

10 oz. Muriate of Tin Crystals.

Mix and strain.

No. 313.

W. ORANGE.

STEAM.

2½ gallons Berry Liquor 12° Twaddle
¾ gallon Sapan Liquor 8° Twaddle.
4 lbs. Starch. Beat up and add
12 oz. White Sugar of Lead, boil, and add
1 qt. X Standard
When half cold add
8 oz. Muriate of Tin Crystals.
Mix and strain.

No. 314.

* 41 P. BLUE.

1½ gallon Water.
2½ lbs. Starch. Boil, and add
6 gallons Pad Blue
Mix and strain.

No. 315.

* WOOD RED.

STEAM.

5 gallons Sapan Liquor 8° Twaddle 1 gallon Berry Liquor 10° Twaddle 1 gallon X Standard 12 lbs. Starch. Boil and add 4 oz. Chloride of Potash Mix and strain.

No. 316.

R. B. PASTE STANDARD.

40 lbs. Sulphate of Zinc. Dissolve in
5 gallons Hot Water, and add
20 lbs. White Sugar of Lead.
Stir till dissolved, and let settle. Use clear liquor.

No. 317.

R. B. PASTE.

1 gallon of the above Liquor 3 lbs. 3 Gum Substitute. Heat to 180°, and strain.

DELAINE COLORS.

DONE AT BARROW.

No. 1.

DELAINE BLACK FOR BLACK AND LAVENDERS, &c.

20 lbs. British Gum. Beat up with

3½ gallons Logwood Liquor 12° Twaddle

2 qts. Acetic Acid

2 lbs. Prussiate of Potash

2 qts. Oil. Boil well and lade out; when nearly cold add

2 qts. Iron Liquor

1 qt. Nitrate of Iron

1 " Muriate of Iron

2 qts. Extract of Indigo.

No. 2.

DELAINE YELLOW.

20 lbs. British Gum

4 gallons Berry Liquor 16° Twaddle

1 qt. Cochineal Liquor 12° Twaddle.

1 " Oil. Boil well and lade.

When nearly cold add

1 lb. Oxalic Acid

1 " Tin Crystals

1 noggin Oxymuriate of Tin.

No. 3.

DELAINE DARK BLUE.

12 lbs. Starch

5 gallons Water

1 gallon Gum Dragon. Boil well

1 gill of Muriate of Iron to darken

2 lbs. Oxalic Acid.

Dissolve in a little Water

10 lbs. Tartaric Acid

4 " Red Prussiate

8 " Prussiate of Potash.

When dissolved add

10 qts. of Tin Pulp

No. 4.

TIN PULP.

Take 24 lbs. Yellow Prussiate, dissolve in 5 gallons of Water (Hot), when dissolved put it in a 100 gallon tub, and add 6 gallons of Cold Water, and stir up; then add 3½ gallons of Muriate of Tin, and keep stirring while the Tin is put in; after the addition of the Tin, fill up with Cold Water, and stir well; then let it settle; and draw the water off; fill up again, and again let it settle; repeat this three times; and then strain for use.

No. 5.

DELAINE DARK GREEN.

14 lbs. Starch

6 gallons Bark Liquor 12° Twaddle.

· Boil and cool.

4 oz. Tin Crystałs

4 lbs. Alum

10 " Prussiate of Potash

6 " Tartaric Acid

4 qts. Extract of Indigo

6 " Tin Pulp.

11*

No. 6.

STRONG P. RED.

8 lbs. Starch
5½ gallons Cochineal Liquor 12° Twaddle
2 qts. of Oil. Boil well and lade
2 "Berry Liquor 16° Twaddle.
When nearly cold add
1½ lb. Oxalic Acid
1¾ "Tin Crystals. Stir very well.

No. 7.

A VERY GOOD DELAINE CHOCOLATE. NO. 1.

22 lbs. Starch

2 " British Gum Pale

3½ gallons Sapan Liquor

11 qts. Bark Liquor 12° Twaddle

1 gallon Logwood Liquor 12° Twaddle

2½ gallons Nitrate of Alumina

2 qts. Oil

10 oz. Chlorate of Potash. Boil well, and turn steam off.

 $2\frac{3}{4}$ oz. Red Prussiate

12 " Tartaric Acid

5 gills of Lime Juice. Stir up well and boil again.

No. 8.

NO. 2 CHOCOLATE, GOOD FOR LIGHT DELAINES.

46 lbs. British Gum

3½ gallons Sapan Liquor 12° Twaddle

23 " Bark Liquor 12° Twaddle

6 qts. Nitrate of Alumina

1 gallon Red Liquor

2 gallons Logwood Liquor 12° Twaddle

1 lb. Chlorate of Potash

2 qts. of Oil. Boil well, turn steam off. Add

33 lbs. Red Prussiate

10 oz. Tartaric Acid.

No. 9.

DELAINE CHOCOLATE DARK.

20 lbs. British Gum

2 gallons Sapan Liquor 12° Twaddle

1 gallon Bark Liquor 12° Twaddle

1 " Logwood Liquor 12° Twaddle

1 " Nitrate of Alumina

6 oz. Chlorate of Potash

2 qts. of Oil. Boil well, turn steam off. Add

13 qt. Red Prussiate

6 oz. Tartaric Acid

5 noggins of Lime Juice.

N. B. The Lime Juice and Tartaric Acid

assist the above Chocolate to wash off soft; as a general rule No. 1 Chocolate is the best. The following is a very Red Chocolate to mix with gale shades for blotche.

No. 10.

DELAINE PALE R. R. CHOCOLATE.

40 lbs. Starch

13 gallons Sapan Liquor 12° Twaddle

4 lbs. British Gum

1 gallon Bark Liquor 12° Twaddle

1 " Logwood Liquor 12° Twaddle

5 gallons Nitrate of Alumina

2 qts. Oil

 $1\frac{1}{4}$ lb. Chlorate of Potash. Boil and turn steam off.

5 lbs. Red Prussiate

 $1\frac{1}{2}$ lb. Tartaric Acid

7 pints Lime Juice.

No. 11.

DELAINE R. R. CHOCOLATE.

20 lbs. Starch

4 " British Gum

5½ gallons Sapan Liquor 12° Twaddle

1 gallon Bark Liquor 12° Twaddle

1 " Logwood Liquor 12° Twaddle

2½ gallons Nitrate of Alumina

10 oz. Chlorate of Potash

3 pints Oil. Boil and turn steam off.

2 lbs. Red Prussiate

1 lb. Tartaric Acid

3 pints Lime Juice.

Boil, stir, and strain.

No. 12.

DELAINE DARK CHOCOLATE B.

40 lbs. Starch

10 " British Gum

5½ gallons Sapan Liquor 12° Twaddle

5½ " Bark Liquor 12° Twaddle

4 " Logwood Liquor 12° Twaddle

5 "Nitrate of Alumina

 $1\frac{1}{2}$ lb. Chlorate of Potash

3 quarts Oil. Boil and turn steam off.

1½ lb. Tartaric Acid

3 qts. Lime Juice.

Boil, stir, and strain.

No. 13.

YELLOW STANDARD FOR LIGHT GREEN STANDARD.

20 lbs. British Gum

3 gallons Berry Liquor 16° Twaddle

1 gallon Bark Liquor 12° Twaddle

5 lbs. Alum

2 qts. Oil.

Boil and lade.

No. 14.

BLUE STANDARD FOR GREEN STANDARD.

2 gallons Gum Senegal

3 gills Muriate of Tin. Put this into one mug.

Then in another mug put

20 lbs. Prussiate of Potash

6 " Alum

3 " Oxalic Acid. Dissolve in

4 gallons Hot Water.

Add the contents of the mug containing the Senegal, &c., to the other very gradually; let some one stir the mixture round briskly.

No. 15.

DELAINE PALE GREEN STANDARD.

6 gallons of the Yellow Standard 1 gallon Extract of Indigo, 13 lbs. 4½ gallons of the Blue Standard.

No. 16.

DELAINE PALE GREEN COLOR No. 3, 3½.

3 gallons Gum Substitute 3½ " Green Standard.



No. 17.

DELAINE GREEN LIGHT 1, 2.

2 gallons Green Substitute 4 "Green Standard.

No. 18.

DELAINE PALE BLUE.

4 gallons Gum Substitute

1 gallon Gum Senegal

2 gallons Dark Blue

1 quart of Tin Pulp

1 pint Extract of Indigo

1½ noggin of Vitriol. When cold add

2 gallons of Gum Substitute.

Stir well and strain.

No. 19.

ANOTHER LIGHT BLUE.

2 gallons Gum Senegal

1 gallon Gum Substitute

1 " Dark Blue

1 pint Extract of Indigo

1 gill of Vitriol.

No. 20.

DELAINE ORANGE (No. 1).

7 lbs. Starch

2 gallons Berry Liquor 16° Twaddle

1 gallon Water

1 " Cochineal 12° Twaddle

3 pints Oil.

Boil well, lade, and stir until cold. Add

1 lb. Oxalic Acid

1 " Tin Crystals.

Stir well and strain.

No. 21.

ANOTHER ORANGE (No. 2).

10 lbs. Starch.

3 gallons Berry Liquor 16° Twaddle

2 gallons Water

1 gallon Cochineal 12° Twaddle

2 qts. Oil.

Boil well, and when nearly cold add

 $1\frac{1}{2}$ lb. Oxalic Acid

1½ " Tin Crystals.

No. 2 Orange is used for light work, and also to mix with Brown Standard.

12

No. 22.

DELAINE BROWN STANDARD.

10 lbs. British Gum

4 quarts Berry Liquor 16° Twaddle

6 " Logwood Liquor 12° Twaddle

2 " Cochineal 12° Twaddle

1 quart Oil.

Boil well, and lade. When nearly cold add

12 oz. Oxalic Acid

12 " Tin Crystals.

Stir well.

Then take

3 gallons of the above Standard

1 gallon of No. 2 Orange.

Stir well for mixing.

No. 23.

No. 3 BROWN.

3 gallons Gum Substitute 1 gallon of the above.

No. 24.

ANOTHER BROWN STANDARD.

22 lbs. British Gum

10 quarts Berry Liquor 16° Twaddle

10 " Logwood Liquor 12° Twaddle

4 " Cochineal 12° Twaddle

2 " Oil.

Boil, and lade, and when nearly cold add

11 lb. Oxalic Acid

1½ " Tin Crystals.

Then take

5 gallons of the above Standard

1 gallon of No. 2 Orange.

No. 25.

No. 4 BROWN.

4 gallons Gum Substitute 1 gallon of the above Standard.

No. 26.

ANOTHER BROWN STANDARD.

32 lbs. British Gum

4 gallons Bark Liquor 12° Twaddle

1½ gallon Sapan Liquor 12° Twaddle

2 gallons Nitrate of Alumina

2 quarts Logwood Liquor 12° Twaddle

2 " Oil.

Boil well and turn steam off. Add

1 lb. Red Prussiate

1 pint Lime Juice.

No. 27.

LIGHT BROWN.

1 gallon Gum Substitute1 " of the above Standard.

No. 28.

Y. BROWN STANDARD.

2 quarts of No. 36 Dark Brown Standard2 " of No. 2 Delaine Yellow.

No. 29.

Y. BROWN.

2 gallons Gum Substitute1 gallon of the above Standard.

No. 30. WOOD COLOR.

7 lbs. Starch

9 quarts Berry Liquor 16° Twaddle

3 " Sapan Liquor 12° Twaddle

2 " Logwood Liquor 12° Twaddle

12 oz. Red Prussiate

3 noggins of Lime Juice

1 quart Oil.

No. 31.

BLACK FOR LIGHT DELAINE.

16 lbs. British Gum

2 gallons Purple Standard

· 2 " Water

5 oz. Chlorate of Potash

3 pints Oil.

Boil well, and lade when nearly cool

1 quart Extract of Indigo.

12*

No. 32.

PURPLE STANDARD.

6 quarts Calico Purple Standard 1 quart Extract of Indigo.

Boil together, and add to the other 6 qts. more of Calico Purple Standard 5 oz. Chlorate of Potash.

No. 33.

No. 12 PURPLE.

6 gallons Gum Substitute ½ gallon of the above Standard.

No. 34.

No. 16 PURPLE.

8 gallons Gum Substitute
2 gallon of the above Purple Standard.

No. 35.

No. 7 PURPLE.

7 gallons Gum Substitute 1 gallon of the above Standard. No. 36.

DARK PURPLE.

24 lbs. British Gum3 gallons Water3 " of the above Standard.

· No. 37.
LAVENDER.

10 gallons Gum Substitute
½ gallon Purple Standard
3 pints of Pale Blue.

No. 38.

No. 8 RED.

19 lbs. Starch

5½ gallons Cochineal 8° Twaddle

2 quarts Berry Liquor 16° Twaddle

2 quarts of Oil.

Boil well, and lade. When nearly cold add $1\frac{1}{2}$ lb. Oxalic Acid. Stir well. Add $1\frac{3}{4}$ "Tin Crystals.

No. 39.

BLACK FOR BLACK AND WHITE.

28 lbs. Starch

13 gallons Logwood 12° Twaddle

2 " Nitrate of Alumina

2 " Iron Liquor

2 "Oil

2½ lbs. of Prussiate.

Boil well, and turn steam off. Add

5 quarts Extract of Indigo

5 " Muriate of Iron

5 " Nitrate of Iron.

No. 40.

ANOTHER GOOD BLACK.

13 lbs. Starch

4 " British Gum

6½ gallons Logwood Liquor 12° Twaddle

2 " Iron Liquor

1 gallon Acetic Acid

1 " Oil

1 lb. 6 oz. Red Prussiate.

Boil and turn steam off. Add

2 quarts Muriate of Iron

2 " Nitrate of Iron.

No. 41.

ANOTHER BLACK.

61 gallons Logwood Liquor 12° Twaddle

2 " Iron Liquor

1 gallon Acetic Acid

½ " Vinegar

1½ lb. Red Prussiate

 $1\frac{1}{2}$ " Chlorate of Potash

½ gallon Extract of Indigo

1 " Oil.

Boil well, and when nearly cool add $\frac{1}{2}$ gallon Muriate of Iron.

No. 42.

PINK.

2 gallons Spirit of Ammonia 11 lbs. of Cochineal (black)

4 gallons of boiling Water. Stand 24 hours and filter; take the grains, and add 4 gallons of boiling Water; boil half an hour; take it off and filter, and make it into 8 gallons altogether, and add

30 lbs. of best White Gum Senegal

8 " Alum

4 " Cream of Tartar

1 qt. Oil

4 oz. Oxalic Acid.

Mix well.

No. 43.

DRAB STANDARD.

B. STANDARD.

2 lbs. Prussiate of Potash
1 lb. Oxalic Acid. Dissolve in
3 qts. boiling Water
1 qt. Nitrate of Alumina.

No. 44.

Y. STANDARD.

gallon Berry Liquor 16° Twaddle
 pint Extract of Indigo
 gallon B. Standard
 quarts Purple Standard.
 Stir well.

No. 45. No. 7 DRAB.

7 gallons Gum Substitute 1 gallon Y. Standard. No. 46.
PALE BLUE.

21 gallons Dark Blue

2 " Gum Senegal

1 pint Extract of Indigo

1 gill Vitriol

4 gallons Gum Substitute

No. 47.

B. GREEN STANDARD.

3 quarts Green Standard, viz. A 11 1 quart Blue Standard for Green 11.

No. 48.

B. GREEN COLOR.

3 gallons Gum Substitute 1 gallon of the above Standard. No. 49.

B. LIQUOR.

- 2 lbs. Oxalic Acid
- 4 " Prussiate of Potash
- 6 quarts boiling Water
- 2 " Nitrate of Alumina. Mix well.

No. 50.

DRAB STANDARD.

- 1 quart Extract of Indigo
- 5 quarts B. Liquor
- 6 " Purple Standard (calico)
- 9 "Berry Liquor 16° Twaddle. Stir well.

No. 51.

DARK DRAB.

6 gallons Gum Substitute 1 gallon of the above Drab Standard. No. 52.

No. 16 DRAB.

8 gallons Gum Substitute 2 quarts Drab Standard.

No. 53.

No. 11 DRAB.

6 gallons Gum Substitute 2 quarts Drab Standard.

No. 54.

No. 10 DRAB.

5 gallons Gum Substitute 2 quarts Drab Standard.

No. 55.

GUM SUBSTITUTE.

4 lbs. British Gum 1 gallon Water. 13 No. 56.

GUM SENEGAL.

6 lbs. Gum Senegal 1 gallon Water.

No. 57.

BLUE STANDARD FOR PADDING.

21 lbs. Prussiate of Potash21 " Tartaric Acid.Reduce to shade.

No. 58.

BLUE FOR PADDING.

4 gallons of the above 2 quarts of Extract 20 gallons Water.

No. 59.

PALE RED FOR DARK RED.

8 qts. of Hervey's Pale Red 1 qt. of No. Bark Liquor.

No. 60. DARK RED.

14 lbs. Starch

6 gallons Cochineal Liquor 12° Twaddle

2 " of the above Pale Red Standard

2 qts. Oil.

Boil well, and add

2 qts. Berry Liquor 16° Twaddle. When cool add

2½ lbs. Oxalic Acid

21 " Tin Crystals.



MADDER COLORS.

No. 1. BLACK.

24 lbs. Flour. Beat it up with 3 gallons Purple Fixing Liquor

3 " Iron Liquor

3 "Water

3 pints Oil.

Dilute with

1 quart Logwood Liquor.

No. 2.

MADDER TIN RED.

28 lbs. Flour. Beat it up with 11 gallons Resist Red Liquor

1 gallon Sapan Liquor

· 1 gill Chrome Liquor at 1 lb. per gallon.

Boil well; when nearly cold add 12 oz. of Tin Crystals per gallon of color. For throwing off No. 2 Chocolate dissolve 1 lb. of Tin per gallon of color.

No. 3.

No. 15 ACID.

18 lbs. of Hervey's No. 2 Dark British Gum3 gallons Lime Juice 20° Twaddle.1 quart Oil.Boil well.

No. 4.

No. 40 ACID.

24 lbs. Dark British Gum. Beat it up with
4 gallons Lime Juice 40° Twaddle
1 quart Oil.
Boil well.

No. 5.

BLACK AND WHITE ACID.

26 lbs. Pale British Gum. Beat it up with

1 gallon Water

7 gallons Lime Juice 40° Twaddle

2 qts. Oil. Boil well and add

2½ lbs. Oxalic Acid.

You may thicken with 10 lbs. best Wheat Starch instead of the Gum.

No. 6.

No. 2 CHOCOLATE.

24 lbs. British Gum
4 gallons Red Liquor
2 " Iron Liquor
1 pint Bark Liquor
1 quart Oil.
Boil well.

No. 7.

No. 3 CHOCOLATE.

16 lbs. British Gum
3 gallons Red Liquor
1 gallon Iron Liquor
1 pint Bark Liquor
1 "Oil.
Boil well.

No. 8.

No. 12 CHOCOLATE.

24 lbs. Flour
12 gallons Red Liquor
1 gallon Iron Liquor
2 qts. Logwood Liquor
2 " Oil.

No. 9.

No. 8 PURPLE.

36 lbs. Pale British Gum
7 gallons Water
1 gallon Purple Fixing Liquor
1 " Iron Liquor
2 qts. Logwood Liquor
1 qt. Oil.

No. 10.

No. 32 PURPLE.

36 lbs. Pale British Gum
7 gallons Water
1 quart of Purple Fixing Liquor
1 " Iron Liquor
1 pint Logwood Liquor
1 qt. Oil.

N. B. If you want to use Ageing Liquor for any of these colors, you must thicken it with $1\frac{1}{2}$ lb. of British Gum per gallon, to be used in the following proportion:—
For No. 8 Purple, 3 pts. per gallon

" No. 2 Chocolate, 3 pts. per gallon

" No. 12 Black, 5 qts. per gallon.

No. 11.

CATECHU BROWN.

24 lbs. Catechu

6½ gallons Water

6 qts. Acetic Acid. Dissolve, strain, and add

3 " Nitrate of Copper 88° Twaddle

1 qt. Acetate of Copper.

Boil 45 minutes; settle and strain; thicken with Gum Senegal at 5 lbs. per gallon.

No. 12.

ACETATE OF COPPER.

2 lbs. White Sugar of Lead4 "Blue Stone

1 gallon boiling Water.

No. 13.

No. 12 RED.

24 lbs. Flour

8 gallons Common Red Liquor

3 " Water

1 gallon Sapan Liquor

1 oz. Chrome

2 qts. Oil.

Boil well.

No. 14. RED STANDARD.

32 lbs. Alum34 " White Sugar of Lead8 gallons boiling Water.Settle.

No. 15.

No. 8 PINK.

8 gallons Gum Substitute1 gallon of the above Red Liquor1 pint Berry Liquor.Stir up well.

No. 12 pink, 14, 16, 20, 24, are made in the same way.

No. 16.

ACID FOR CUTTING PINKS.

2 qts. of Vitriol 6 "Oxymuriate of Tin.

No. 17.

RED PASTE FOR BLOCKING.

20 lbs. Pale British Gum

6 " Flour

4½ gallons Red Liquor


4 " Water

2 qts. Sapan Liquor ·

½ oz. Chrome.







Practical and Scientific Books,

PUBLISHED BY

HENRY CAREY BAIRD,

INDUSTRIAL PUBLISHER,

No. 406 Walnut Street, PHILADELPHIA.

Any of the following Books will be sent by mail, free of postage, at the publication price. Catalogues furnished on application.

American Miller and Millwright's Assistant:

A new and thoroughly revised Edition, with additional Engravings. By William Carter Hughes. In one volume, 12 mo., \$1.25

Armengaud, Amoroux, and Johnson.

THE PRACTICAL DRAUGHTSMAN'S BOOK OF INDUSTRIAL DESIGN, and Machinist's and Engineer's Drawing Companion; forming a complete course of Mechanical Engineering and Architectural Drawing. From the French of M. Armengaud the elder, Prof. of Design in the Conservatoire of Arts and Industry, Paris, and MM. Armengaud the younger, and Amouroux, Civil Engineers. Rewritten and arranged, with additional matter and plates, selections from and examples of the most useful and generally employed mechanism of the day. By William Johnson, Assoc. Inst. C. E., Editor of "The Practical Mechanic's Journal." Illustrated by fifty folio steel plates and fifty wood-cuts. A new edition, 4to.,...\$10.00

Among the contents are:—Linear Drawing, Definitions and Problems, Plate I. Applications, Designs for inlaid Pavements, Ceilings and Balconies, Plate II. Sweeps, Sections and Mouldings, Plate III. Elementary Gothic Forms and Rosettes, Plate IV. Ovals, Ellirses,

Parabotas and Volutes, Plate V. Rules and Practical Data. Study of Projections, Elementary Principles, Plate VI. Of Prisms and other Solids, Plate VII. Rules and Practical Data. On Coloring Sections, with Applications—Conventional Colors, Composition or Mixture of Colors, Plate X. Continuation of the Study of Projections—Use of sections—details of machinery, Plate XI. Simple applications—spindles, shafts, couplings, wooden patterns, Plate XII. Method of constructing a wooden model or pattern of a coupling, Elementary applications—rails and chairs for railways, Plate XIII. Rules and Practical Data—Strength of material, Resistance to compression or crushing force, Tensional Resistance, Resistance to flexure, Resistance to torsion, Friction of surfaces in contact.

THE INTERSECTION AND DEVELOPMENT OF SURFACES, WITH APPLICATIONS.—The Intersection of Cylinders and Cones, Plate XIV. The Delineation and Development of Helices, Screws and Serpentines, Plate XV. Application of the helix—the construction of a staircase, Plate XVI. The Intersection of surfaces.—applications to stop-cocks, Plate XVII. Rules and Practical Data—Steam, Unity of heat, Heating surface, Calculation of the dimensions of boilers, Dimensions of firegrates,

Chimneys, Safety-valves.

THE STUDY AND CONSTRUCTION OF TOOTHED GEAR.—Involute, cycloid, and epicycloid, Plates XVIII. and XIX. Involute, Fig. 1, Plate XVIII. Cycloid, Fig. 2, Plate XVIII. External epicycloid, described by a circle rolling about a fixed circle inside it, Fig. 3, Plate XIX. Internal epicycloid, Fig. 2, Plate XIX. Delineation of a rack and pinion in gear, Fig. 4, Plate XVIII. Gearing of a worm with a worm-wheel, Figs. 5 and 6, Plate XVIII. Cylindrical or Spur Gearing, Plate XIX. Practical delineation of a couple of Spur-wheels, Plate XXI. The Delineation and Construction of Wooden Patterns for Toothed Wheels, Plate XXI. Rules and Practical Data—Toothed gearing, Angular and circumferential velocity of wheels, Dimensions of gearing, Thickness of the teeth, Pitch of the teeth, Dimensions of the web, Number and dimensions of the arms, wooden patterns.

CONTINUATION OF THE STUDY OF TOOTHED GEAR.—Design for a pair of bevel-wheels in gear, Plate XXII. Construction of wooden patterns for a pair of bevel-wheels, Plate XXIII. Involute and Helical Teeth, Plate XXIV. Contrivances for obtaining Differential Movements—The delineation of eccentrics and cams, Plate XXV. Rules and Practical Data—Mechanical work of effect, The simple machines, Centre of gravity, On estimating the power of prime movers, Calculation for the brake, The fall of bodies, Momentum, Central forces.

ELEMENTARY PRINCIPLES OF SHADOWS.—Shadows of Prisms, Pyramids and Cylinders, Plate XXVI. Principles of Shading, Plate XXVII. Continuation of the Study of Shadows, Plate XXVIII. Tuscan Order, Plate XXIX. Rules and Practical Data—Pumps, Hydrostatic principles, Forcing pumps, Lifting and forcing pumps, The Hydrostatic principles, Hydrostatical calculations and data—discharge of water through different orifices, Gaging of a water-courses of uniform section and fall, Velocity of the bottom of water-courses, Calculation of the discharge of water through rectangular orifices of narrow edges, Calculation of the discharge of water through overshot outlets, To determine the width of an overshot outlet, To determine the depth of the outlet, Outlet with a spout or duct.

APPLICATION OF SHADOWS TO TOOTHED GEAR, Plate XXX. Application of Shadows to Screws, Plate XXXI. Application of Shadows to a Boiler and its Furnace, Plate XXXII. Shading in Black—Shading in

Colors, Plate XXXIII.

THE CUTTING AND SHAPING OF MASONRY, Plate XXXIV. Rules and Practical Data—Hydraulic motors, Undershot water wheels, with plane floats and a circular channel, Width, Diameter, Velocity, Number and capacity of the buckets, Useful effect of the water wheel, Overshot water wheels, Water wheels with radial floats, Water wheel with curved buckets, Turbines. Remarks on Machine Tools.

THE STUDY OF MACHINERY AND SKETCHING .- Various applications and combinations: The Sketching of Muchinery, Plates XXXV. and XXXVI. Drilling Machine; Motive Machines; Water wheels, Con-XXXVI. Drilling Machine; Moltive Machines; Water wheels, Construction and setting up of water wheels, Delineation of water wheels, Design for a water wheel, Sketch of a water wheel; Overshot Water Wheels. Water Pumps, Plate XXXVII. Steam Motors; High-pressure expansive steam engine, Plates XXXVIII., XXXIX. and XL. Details of Construction; Movements of the Distribution and Expansion Valves; Rules and Practical Data—Steam engines: Low-pressure condensing engines without expansion valve, Diameter of piston, Velocities, Steam pipes and passages, Air-pump and condenser, Cold-water and feed-pumps, High-pressure expansive engines, Medium pressure condensing and expansive steam engine, Conical pendulum or centrifugal governor.

Oblique Projections.—Application of rules to the delineation of an oscillating cyfinder, Plate XLI.

PARALLEL PERSPECTIVE.—Principles and applications, Plate XLII.
TRUE PERSPECTIVE.—Elementary principles, Plate XLIII. Applications—flour mill driven by belts, Plates XLIV. and XLV. Description of the mill, Representation of the mill in perspective, Notes of recent improvements in fiour mills, Schiele's mill, Mullin's "ring millstone," Barnett's millstone, Hastie's arrangement for driving mills, Currie's improvements in millstones; Rules and Practical Data—Work performed by various mechanics. Elong mills Song mills. Venore saving performed by various machines, Flour mills, Saw mills, Veneer-sawing

periotined by various machines, rour mins, saw mins, veneer-sawing machines, Circular saws.

EXAMPLES OF FINISHED DRAWINGS OF MACHINERY.—Plate A, Balance water-meter; Plate B, Engineer's shaping machine; Plate C D E, Express locomotive engine; Plate F, Wood planing machine; Plate G, Washing machine for piece goods; Plate H, power loom; Plate I, Duplex steam boiler; Plate J, Direct-acting marine engines.

DRAWING INSTRUMENTS.

Blinn. A Practical Workshop Companion for Tin, Sheet-Iron, and Copper-Plate Workers:

Containing Rules for Describing various kinds of Patterns used by Tin, Sheet-Iron, and Copper-Plate Workers; Practical Geometry; Mensuration of Surfaces and Solids; Tables of the Weights of Metals, Lead Pipe, etc.; Tables of Areas and Circumferences of Circles; Japans, Varnishes, Lackers, Cements, Compositions, etc. etc. By Leroy J. With numerous Illustrations. 12mo......\$2.50

Beans. A Treatise on Railroad Curves and the Location of Railroads.

By E. W. Beans, C. E. 12mo. (In press.)

Bishop. A History of American Manufactures,

From 1608 to 1860; exhibiting the Origin and Growth of the Principal Mechanic Arts and Manufactures, from the Earliest Colonial Period to the Present Time; with a

Bookbinding: A Manual of the Art of Book binding,

Containing full instructions in the different branches of Forwarding, Gilding and Finishing. Also, the Art of Marbling Book-edges and Paper. By James B. Nicholson. Illustrated. 12mo., cloth, \$2.25

CONTENTS.—Sketch of the Progress of Bookbinding, Sheetwork, Forwarding the Edges, Marbling, Gilding the Edges, Covering, Half Binding, Blank Binding, Boarding, Cloth-work, Ornamental Art, Finishing, Taste and Design, Styles, Gilding, Illuminated Binding, Blind Tooling, Antique, Coloring, Marbling, Uniform Colors, Gold Marbling, Landscapes, etc., Inlaid Ornaments, Harmony of Colors, Pasting Down, etc., Stamp or Press-work, Restoring the Bindings of Old Books, Supplying imperfections in Old Books, Hints to Book Collectors, Technical Lessons.

Booth and Morfit. The Encyclopedia of Chemistry, Practical and Theoretical:

From the very large number of articles in this volume, it is entirely impossible to give a list of the Contents, but attention may be called to some among the more elaborate, such as Affinity, Alcoholometry, Ammonium, Analysis, Antimony, Arsenic, Blowpipes, Cyanogen, Distillation, Electricity, Ethyl, Fermentation, Iron, Lead and Water.

Brewer; (The Complete Practical.)

Or Plain, Concise, and Accurate Instructions in the Art of Brewing Beer, Ale, Porter, etc., etc., and the Process

Many an old brewer will find in this book valuable hints and sug-

gestions worthy of consideration, and the novice can post himself up In his trade in all its parts."—Artisan.

Builder's Pocket Companion:

Containing the Elements of Building, Surveying, and Architecture: with Practical Rules and Instructions connected with the subject. By A. C. SMEATON, Civil Engi-In one volume, 12mo.,\$1.25

CONTENTS.—The Builder, Carpenter, Joiner, Mason, Plasterer, Plumber, Painter, Smith, Practical Geometry, Surveyor, Cohesive Strength of Bodies, Architect.

"It gives, in a small space, the most thorough directions to the builder, from the laying of a brick, or the felling of a tree, up to the most elaborate production of ornamental architecture. It is scientific, without being obscure and unintelligible; and every house-carpenter, master, journeyman, or apprentice, should have a copy at hand always."—Evening Bulletin.

The Handbook for the Artisan, Me-Byrne. chanic, and Engineer,

Containing Instructions in Grinding and Sharpening of Cutting Tools, Figuration of Materials by Abrasion, Lapidary Work, Gem and Glass Engraving, Varnishing and Lackering, Abrasive Processes, etc., etc. By Oliver Byrne. Illustrated with 11 large plates and 185 cuts. 8vo., cloth,.....

CONTENTS.—Grinding Cutting Tools on the Ordinary Grindstone; Sharpening Cutting Tools on the Oilstone; Setting Razors; Sharpening Cutting Tools with Artificial Grinders; Production of Plane Surfaces by Abrasion; Production of Cylindrical Surfaces by Abrasion; Production of Spherical Surfaces by Abrasion; Production of Spherical Surfaces by Abrasion; Cutting; Lapidary Work; Setting, Cutting, and Polishing Flat and Rounded Works; Cutting Faucets; Lapidary Apparatus for Amateurs; Gem and Glass Engraving; Seal and Gem Engraving; Cameo Cutting; Glass Engraving; Varnishing, and Lackering; General Remarks upon Abrasive Processes; Dictionary of Apparatus; Materials and Processes for Grinding and Polishing commonly employed in the Mechanical and Useful Arts.

Byrne. The Practical Metal-worker's Assistant.

For Tin-plate Workers, Braziers, Coppersmiths, Zincplate Ornrmenters and Workers, Wire Workers, Whitesmiths, Blacksmiths, Bell Hangers, Jewellers, Silver and Gold Smiths, Electrotypers, and all other Workers in Alloys and Metals. Edited by OLIVER BYRNE. Complete in one volume, octavo,.....\$7.00

It treats of Casting, Founding, and Forging; of Tongs and other Tools; Degrees of Heat and Management of Fires; Welding of

Heading and Swage Tools; of Punches and Anvils; of Hardening and Tempering; of Malleable Iron Castings, Case Hardening, Wrought and Cast Iron; the Management and Manipulation of Metals and Alloys, Melting and Mixing; the Management of Furnaces, Casting and Founding with Metallic Moulds, Joining and Working Sheet Metal; Peculiarities of the different Tools employed; Processes dependent on the ductility of Metals; Wire Drawing, Drawing Metal Tubes, Soldering; The use of the Blowpipe, and every other known Metal Worker's Tool.

Byrne. The Practical Model Calculator,

For the Engineer, Machinist, Manufacturer of Engine Work, Naval Architect, Miner, and Millwright. By OLIVER BYRNE, Compiler and Editor of the Dictionary of Machines, Mechanics, Engine Work and Engineering, and Author of various Mathematical and Mechanical Works. Illustrated by numerous engravings. Complete in one large volume, octavo, of nearly six hundred pages, ...\$4.50

The principal objects of this work are: to establish model calculations to guide practical men and students; to illustrate every practical rule and principle by numerical calculations, systematically arranged; to give information and data indispensable to those for whom it is intended, thus surpassing in value any other book of its character; to economize the labor of the practical man, and to render his every-day calculations easy and comprehensive. It will be found to be one of the most complete and valuable practical books ever published.

Cabinetmaker's and Upholsterer's Companion,

concerned in those branches of business." Campin. A Practical Treatise on Mechanical

Engineering;

Comprising Metallurgy, Moulding, Casting, Forging, Tools, Workshop Machinery, Mechanical Manipulation, Manufacture of Steam Engines, etc. etc. With an Appendix on the Analysis of Iron and Iron Ores. By Francis Campin, C. E. To which are added, Observations on the

-6

Colburn. The Locomotive Engine;

"It is the most practical and generally useful work on the Steam Engine that we have seen."—Boston Traveler."

Daguerreotypist and Photographer's Companion.

Distiller (The Complete Practical).

By M. LAFAYETTE BYRN, M.D. With Illustrations. 12mo. \$1.25

"So simplified that it is adapted not only to the use of extensive Distillers, but for every farmer, or others who may want to engage in Distilling."—Banner of the Union.

Dussauce. Practical Treatise

ON THE FABRICATION OF MATCHES, GUN COTTON, AND FULMINATING POWDERS. By Prof. H. Dussauce. 12mo.,....\$3.00

CONTENTS.—Phosphorus.—History of Phosphorus; Physical Properties; Chemical Properties; Natural State; Preparation of White Phosphorus; Amorphous Phosphorus, and Benoxide of Lead. Matches.—Preparation of Wooden Matches; Matches inflammable by rubbing, without noise; Common Lucifer Matches: Matches without Phosphorus; Candle Matches; Matches with Amorphous Phosphorus; Matches and Rubbers without Phosphorus. Gun Cotton.—Properties; Preparation; Paper Powder; use of Cotton and Paper Powders for Fulminating Primers, etc., etc., etc., etc., etc., etc., etc., etc.

Dussauce. Chemical Receipt Book:

A General Formulary for the Fabrication of Leading Chemicals, and their Application to the Arts, Manufactures, Metallurgy, and Agriculture. By Prof. H. Dussauce. (In press.)

DYEING, CALICO PRINTING, COLORS, COTTON SPIN-NING, AND WOOLEN MANUFACTURE,

The American Cotton Spinner, and Manager's and Carder's Guide:

A Practical Treatise on Cotton Spinning; giving the Dimensions and Speed of Machinery, Draught and Twist Calculations, etc.; with Notices of recent Improvements: together with Rules and Examples for making changes in the sizes and numbers of Roving and Yarn. Compiled from the papers of the late Robert H. Baird.

Capron De Dole. Dussauce. Blues and Carmines of Indigo:

A Practical Treatise on the Fabrication of every Commer cial Product derived from Indigo. By Felicien Capron de Dole. Translated, with important additions, by Professor H. Dussauce. 12mo......\$2.50

Chemistry Applied to Dyeing.

By James Napier, F. C. S. Illustrated, 12mo......\$2.50

By James Napier, F. C. S. Illustrated. 12mo......\$2.50 CONTENTS.—General Properties of Matter.—Heat, Light, Elements of Matter, Chemical Affinity. Non-Metallic Substances.—Oxygen, Hydrogen, Nitrogen, Chlorine, Sulphur, Selenium, Phosphorus, Iodine, Bromine, Fluorine, Silicum, Boron, Carbon. Metallic Substances.—General Properties of Metals, Potassium, Sodium, Lithium, Soap, Barium, Strontium, Calcium, Magnesium, Alminum, Manganese, Iron, Cobalt, Nickel, Zinc, Cadmium, Copper, Lead, Bismuth, Tin, Titanium, Chromium, Vanadium, Tungstenum or Wolfram, Molybdenum, Tellerium, Arsenic, Antimony, Uranium, Cerium, Mercury, Silver, Gold, Platinum, Palladium, Iridium, Osmium, Rhodium, Lanthanium. Mardants.—Red Spirits, Barwood Spirits, Plumb Spirits, Yellow Spirits, Nitrate of Iron, Acetate of Alumina, Black Iron Liquor, Iron and Tin for Royal Blues, Acetate of Copper. Vegetable Matters used in Dyeing.—Galls, Sumach, Catechu, Indigo, Logwood, Brazil-woods, Sandal-wood, Barwood, Camwood, Fustic, Young Fustic, Bark or Quercitron, Flavine, Weld or Wold, Turmeric, Persian Berries, Safflower, Madder, Munjeet, Annota, Alkanet Root, Archil. Proposed New Vegetable Dyes.—Sooranjee, Carajuru, Wongshy, Aloes, Pittacal, Barbary Root, Animal Matters used in Dyeing.—Cochineal, Lake or Lac, Kerms.

This will be found one of the most valuable books on the subject of dyeing, ever published in this country.

Dussauce. Treatise on the Coloring Matters Derived from Coal Tar:

Their Practical Application in Dyeing Cotton, Wool, and

Dyer and Color-maker's Companion:

French Dyer, (The):

Comprising the Art of Dyeing in Woolen, Silk, Cotton, etc., etc. By M. M. Riffault, Vernaud, De Fontenelle, Thillaye, and Mallepeyre. (In press.)

Love. The Art of Dyeing, Cleaning, Scouring, and Finishing,

ON THE MOST APPROVED ENGLISH AND FRENCH METHODS; being Practical Instructions in Dyeing Silks, Woolens and Cottons, Feathers, Chips, Straw, etc., Scouring and Cleaning Bed and Window Curtains, Carpets, Rugs, etc., French and English Cleaning, any Color or Fabric of Silk, Satin, or Damask. By Thomas Love, a working Dyer and Scourer. In one volume, 12mo.........\$3.00

O'Neill. Chemistry of Calico Printing, Dyeing, and Bleaching;

Including Silken, Woolen, and Mixed Goods; Practical and Theoretical. By Charles O'Neill. (In press.)

O'Neill. A Dictionary of Calico Printing and Dyeing.

By Charles O'Neill. (In press.)

Scott. The Practical Cotton-spinner and Manufacturer;

This edition of Scott's Cotton-Spinner, by Oliver Byrne, is designed for the American Operative. It will be found intensely practical, and will be of the greatest possible value to the Manager, Overseer, and Workman.

Sellers. The Color-mixer.

Smith. The Dyer's Instructor;

Comprising Practical Instructions in the Art of Dyeing Silk, Cotton, Wool and Worsted, and Woolen Goods, as Single and Two-colored Damasks, Moreens, Camlets, Lastings, Shot Cobourgs, Silk Striped Orleans, Plain Orleans, from White and Colored Warps, Merinos, Woolens, Yarns, etc.; containing nearly eight hundred Receipts. To which is added a Treatise on the Art of Padding, and the Printing of Silk Warps, Skeins and Handkerchiefs, and the various Mordants and Colors for the different

Ulrich. Dussauce. A Complete Treatise

ON THE ART OF DYEING COTTON AND WOOL, AS PRACTISED IN PARIS, ROUEN, MULHOUSE AND GERMANY. From the French of M. Louis Ulrich, a Practical Dyer in the principal Manufactories of Paris, Rouen, Mulhouse, etc., etc.; to which are added the most important Receipts for Dyeing Wool, as practised in the Manufacture Imperiale des Gobelins, Paris. By Professor H. Dussauce. 12mo..\$3.00 CONTENTS.—

ROUEN Dyes, 106 Receipts.

Alsace " 235 "
German " 109 "
Mulhouse " 72 "
Parisian " 56 "
Gobelans " 100 "

In all nearly 700 Receipts.

Easton. A Practical Treatise on Street or Horse-power Railways;

Their Location, Construction and Management; with general Plaus and Rules for their Organization and Operation; together with Examinations as to their Compara-

tive Advantages over the Omnibus System, and Inquiries
as to their Value for Investment; including Copies of
Municipal Ordinances relating thereto. By Alexander
Easton, C. E. Illustrated by twenty-three plates, 8vo.,
cloth\$2.00

Examinations of Drugs, Medicines, Chemicals, etc.,

Fisher's Photogenic Manipulation.

16mo., cloth....... 62

Gas and Ventilation;

Gilbart. A Practical Treatise on Banking.

Gregory's Mathematics for Practical Men;

Adapted to the Pursuits of Surveyors, Architects, Mechanics and Civil Engineers. 8vo., plates, cloth...\$2.25

Hardwich. A Manual of Photographic Chemistry;

Including the practice of the Collodion Process. By J. F. Hardwich. (In press.)

Hav. The Interior Decorator;

The Laws of Harmonious Coloring adapted to Interior Decorations; with a Practical Treatise on House Painting. By D. R. Hay, House Painter and Decorator. Illustrated by a Diagram of the Primary, Secondary and Tertiary Colors. 12mo. (In press.)

Inventor's Guide—Patent Office and Patent Laws:

Jervis. Railway Property. A Treatise

ON THE CONSTRUCTION AND MANAGEMENT OF RAILWAYS; designed to afford useful knowledge, in the popular style, to the holders of this class of property; as well as Railway Managers, Officers and Agents. By John B. Jervis, late Chief Engineer of the Hudson River Railroad, Croton Aqueduct, etc. One volume, 12mo., cloth......\$2.00

CONTENTS. — Preface — Introduction. — Construction. — Introductory—Land and Land Damages—Location of Line—Method of Business—Grading—Bridges and Culverts—Road Crossings—Ballasting Track—Cross Sleepers—Chairs and Spikes—Rails—Station Buildings—Locomotives, Coaches and Cars. Operating.—Introductory—Freight—Passengers—Engine Drivers—Repairs to Track—Repairs of Machinery—Civil Engineer—Superintendent—Supplies of Material—Receipts—Disbursements—Statistics—Running Trains—Competition—Financial Management—General Remarks.

Johnson. The Coal Trade of British America;

With Researches on the Characters and Practical Values of American and Foreign Coals. By Walter R. Johnson, Civil and Mining Engineer and Chemist. 8vo.......\$2.00 This volume contains the results of the experiments made for the Navy Department, upon which their Coal contracts are now based.

Johnston. Instructions for the Analysis of Soils, Limestones and Manures.

By J. F. W. Johnston. 12mo...... 38

Larkin. The Practical Brass and Iron Founder's Guide;

A Concise Treatise on the Art of Brass Founding, Moulling, etc. By James Larkin. 12mo., cloth..........\$1.25

Leslie's (Miss) Complete Cookery;

1	A Manu	al of Do	mestic Eco		BOOK;	
I	æslie's Fr	(Miss) Two	Hundred	l Receipts	in
			_		•••••••••	

Lieber. Assayer's Guide;

"Among the indispensable works for this purpose, is this little guide."—Artizan.

Lowig. Principles of Organic and Physiological Chemistry.

Marble Worker's Manual;

Miles. A Plain Treatise on Horse shoeing. With Illustrations. By William Miles, Author of "The

Horse's Foot.'.....\$1.00

Main & Brown. The Marine Steam Engine.

By Thomas J. Main, F.R. Ast. S. Mathematical Professor at the Royal Naval College, Portsmouth, and Thomas Brown, Assoc. Inst. C. E. Chief Engineer R. N. attached to the Royal Naval College. Authors of "Questions Connected with the Marine Steam-Engine," and the "Indicator and Dynamometer." With Numerous Illustrations. In one Volume, 8vo......\$5.00

CONTENTS.—Introductory Chapter, The Boiler, The Engine, Getting up Steam, Duties to Machinery when under Steam, Duties to Engine, &c., on arriving in harbor, Miscellaneous, Appendix.

Main & Brown. Questions on Subjects Connected with the Marine Steam Engine,

And Examination Papers; with Hints for their Solution. By Thomas J. Main, Professor of Mathematics Royal Naval College, and Thomas Brown, Chief Engineer R. N. 12mo.,

Main & Brown. The Indicator and Dynamo. meter.

With their Practical Applications to the Steam Engine. By Thomas J. Main and Thomas Brown. With Illustrations. 8vo., cloth......\$1.50

Morfit. A Treatise on Chemistry

Applied to the Manufacture of Soap and Candles; being a Thorough Exposition, in all their Minutiæ, of the principles and Practice of the Trade, based upon the most recent Discoveries in Science and Art. By Campbell Morfit, Professor of Analytical and Applied Chemistry in the University of Maryland. A new and improved edition. Illustrated with 260 Engravings on Wood. Complete in one volume, large 8vo......\$7.50

CONTENTS,—CHAPTER I. The History of the Art and its Relations to Science—II. Chemical Combination—III. Alkalies and Alkaline Earths—IV. Alkalimentary—V. Acids—VI. Origin and Composition of Fatty Matters—VII. Saponifiable Fats—View Patty Matters—VIII. Action of Heat and Mineral Acids of Fatty Matters—IX. Volatile or Essential Oils, and Resins—X. The Proximate Principles of Fats—Their Composition and Properties—Basic Constituents of Fats—XI. Theory of Saponification—XII. Utensils Requisite for a Soap Factory—XIII. Preparatory Manipulations in the Process of Making Soap—Preparation of the Lyes—XIV. Hard

Soaps—XV. Soft Soaps—XVI. Soaps by the Cold Process—XVII. Silicated Soaps—XVIII. Toilet Soaps—XIX. Patent Soaps—XX. Fraud and Adulterations in the Manufacture of Soap—XXI. Candles—XXII. Illumination—XXIII. Philosophy of Flame—XXIV. Raw Material for Candles—Purification and Bleaching of Suet—XXV. Wicks—XXVI. Dipped Candles—XXVII. Moulded Candles—XXVIII. Stearin Candles—XXII. Stearic Acid Candles—"Star" or "Adamantine" Candles—Saponification by Lime—Saponification by Lime—Saponification by Lime—Saponification by the combined action of Heat, Pressure and Steam—XXX. Spermaceti Candles—XXXI. Wax Candles—XXXII. Composite Candles—XXXIII. Paraffin—XXXIV. Patent Candles—XXXV. Hydrometers and Thermometers.

Pyrotechnist's Companion; Mortimer.

Or, a Familiar System of Fire-works. By G. W. Mortimer. Illustrated by numerous Engravings. 12mo \$1.25

Manual of Electro-Metallurgy;

Including the Application of the Art to Manufacturing Processes. By James Napier. From the second London edition, revised and enlarged. Illustrated by Engravings. In one volume, 12mo.......\$1.50

Napier's Electro-Metallurgy is generally regarded as the very best Practical Treatise on the Subject in the English Language.

CONTENTS.—History of the Art of Electro-Metallurgy—Description of Galvanic Batteries, and their respective Peculiarities—Electrotype Processes—Miscellaneous Applications of the Process of Coating with Copper—Bronzing—Decomposition of Metals upon one another—Electro-Plating—Electro-Gilding—Results of Experiments on the Deposition of other Metals as Coatings, Theoretical Observations

Norris's Hand-book for Locomotive Engineers and Machinists:

Comprising the Calculations for Constructing Locomotives, Manner of setting Valves, etc., etc. By Septimus Norris, Civil and Mechanical Engineer. In one volume, 12mo., with Illustrations......\$2.00

"With pleasure do we meet with such a work as Messrs. Norris and Baird have given us."—Artizan.
"In this work he has given us what are called 'the secrets of the business,' in the rules to construct locomotives, in order that the million should be learned in all things."—Scientific American.

Nystrom. A Treatise on Screw-Propellers and their Steam-Engines:

With Practical Rules and Examples by which to Calculate and Construct the same for any description of Vessels. By J. W. Nystrom. Illustrated by over thirty large Working Drawings. In one volume, octavo...\$6.00

Overman. The Manufacture of Iron in all its Various Branches;

"We have now to announce the appearance of another valuable work on the subject, which, in our humble opinion, supplies any deficiency which late improvements and discoveries may have caused, from the lapse of time since the date of 'Mushet' and 'Schrivenor.' It is the production of one of our Trans-Atlantic brethren, Mr. Frederick Overman, Mining Engineer; and we do not hesitate to set it down as a work of great importance to all connected with the iron interests; one which, while it is sufficiently technological fully to explain chemical analysis, and the various phenomena of iron under different circumstances, to the satisfaction of the most fastidious, is written in that clear and comprehensive style as to be available to the capacity of the humblest mind, and consequently will be of much advantage to those works where the proprietors may see the desirability of placing it in the hands of their operatives."—London Mining Journal.

Painter, Gilder and Varnisher's Companion;

Paper Hanger's (The) Companion;

In which the Practical Operations of the Trade are systematically laid down; with copious Directions Preparatory to Papering; Preventions against the effect of Damp in Walls; the various Cements and Pastes adapted to the several purposes of the Trade; Observations and Directions for the Panelling and Ornamenting of Rooms, etc., etc. By James Arrowsmith. In one volume 12mo \$1.25

Practical (The) Surveyor's Guide;

Containing the necessary information to make any per son of common capacity a finished Land Surveyor, with-

Having had an experience as a Practical Surveyor, etc., of thirty years, it is believed that the author of this volume possesses a thorough knowledge of the wants of the profession; and never having met with any work sufficiently concise and instructive in the several details necessary for the proper qualification of the Surveyor, it has been his object to supply that want. Among other important matters in the

book, will be found the following:

Instructions in levelling and profiling, with a new and speedy plan of setting grades on rail and plank roads—the method of infecting curves—the description and design of a new instrument, whereby distances are found at once, without any calculation—a new method of surveying any tract of land by measuring one line through it—a geometrical method of correcting surveys taken with the compass, to fit them for calculation—a short method of finding the angles from the courses, and vice versa—the method of surveying with the compass through any mine or iron works, and to correct the deflections of the needle by attraction—description of an instrument by the help of which any one may measure a map by inspection, without calculation—a new and short method of calculation, wherein fewer figures are used—the method of correcting the diurnal variation of the needle—various methods of plotting and embellishing maps—the most correct method of laying off plots with the pole, etc.—description of a new compass contrived by the author, etc., etc.

Railroad Engineer's Pocket Companion for the Field.

By W. Griswold. 12mo., tucks......\$1.25

Regnault. Elements of Chemistry.

Rural Chemistry;

Shunk. A Practical Treatise

ON RAILWAY CURVES, AND LOCATION FOR YOUNG ENGINEERS. By Wm. F. Shunk, Civil Engineer. 12mo............\$1.00

Strength and Other Properties of Metals;

Roports of Experiments on the Strength and other Pro-

The best Treatise on Cast-iron extant.

Tables Showing the Weight

Taylor. Statistics of Coal;

Templeton. The Practical Examinator on Steam and the Steam Engine;

This work was originally written for the author's private use. He was prevailed upon by various Engineers, who had seen the notes, to consent to its publication, from their eager expression of belief that it would be equally useful to them as it had been to himself.

Tin and Sheet Iron Worker's Instructor;

Treatise (A) on a Box of Instruments,

And the Slide Rule; with the Theory of Trigonometry and Logarithms, including Practical Geometry, Surveying, Measuring of Timber, Cask and Malt Gauging,

A volume of inestimable value to Engineers, Gaugers, Students, and others.

Turnbull. The Electro-Magnetic Telegraph;

With an Historical Account of its Rise, Progress, and Present Condition. Also, Practical Suggestions in regard to Insulation and Protection from the Effects of Lightning. Together with an Appendix containing several important Telegraphic Devices and Laws. By Lawrence Turnbull, M. D., Lecturer on Technical Chemistry at the Franklin Institute. Second edition. Revised and improved. Illustrated by numerous Engravings. 8vo..\$2.50

Turner's (The) Companion;

Containing Instruction in Concentric, Elliptic and Eccentric Turning; also various Steel Plates of Chucks, Tools and Instruments; and Directions for Using the Eccentric Cutter, Drill, Vertical Cutter and Rest; with Patterns and Instructions for working them. 12mo., cloth.. \$1.25

Weatherley (Henry). Treatise on the Art of Boiling Sugar, Crystallizing, Lozenge making, Comfits, Gum Goods,

 $12 \mathrm{mo......}$ \$2.0 c

Williams. On Heat and Steam:

Embracing New Views of Vaporization, Condensation, and Expansion. By Charles Wye Williams. Illustrated.

SOCIAL SCIENCE. THE WORKS OF HENRY C. CAREY.

[&]quot;I challenge the production from among the writers on political economy of a more learned, philosophical, and convincing speculator on that theme, than my distinguished fellow-citizen, Henry C. Carey. The works he has published in support of the protective policy, are remarkable for profound research, extensive range of inquiry, rare logical acumen, and a consummate knowledge of history."—Speech of Hon. Edward Joy Morris, in the House of Representatives of the United States, February 2, 1859.

"Henry C. Carey, the best known and ablest economist of North America. * * * * * In Europe he is principally known by his striking and original attacks, based upon the peculiar advantages of American experience, on some of the principal doctrines, especially Malthus' 'Theory of Population' and Ricardo's teachings. His views have been largely adopted and thoroughly discussed in Europe."— "The German Political Lexicon," Edited by Bluntschli and Brater. Leipsic, 1858.

"We believe that your labors mark an era in the science of political economy. To your researches and luqid arguments are we indebted for the explosion of the absurdities of Malthus, Say, and Ricardo, in regard to the inability of the earth to meet the demands of a growing population. American industry owes you a debt which cannot be repaid, and which it will ever be proud to acknowledge.—From a Letter of Hon. George W. Scranton, M. C., Hon. William Jessup, and over sixty influential citizens of Luzerne County, Pennsylvania, to Henry C. Carey, April 3, 1859.

Financial Crises;

Their Causes and Effects. Svo., paper...... 25

French and American Tariffs,

Harmony (The) of Interests;

"We can safely recommend this remarkable work to all who wish to investigate the causes of the progress or decline of industrial communities."—Blackwood's Magazine.

Letters to the President of the United States.

8vo., Paper...... 50

Miscellaneous Works;

Comprising "Harmony of Interests," "Money," "Letters to the President," "French and American Tariffs," and "Financial Crises." One volume, 8vo.\$3.00

Money; A Lecture

Past (The), the Present, and the Future.

8vo......\$2.50

- "Full of important facts bearing on topics that are now agitating all Europe. * * * These quotations will only whet the appetite of the scientific reader to devour the whole work. It is a book full of valuable information."-Economist.
- "Decidedly a book to be read by all who take an interest in the progress of social science."—Spectator.
- "A Southern man myself never given to tariff doctrines, I confess to have been convinced by his reasoning, and, thank Heaven, have not now to learn the difference between dogged obstinacy and consistency. 'Ye gods, give us but light! should be the motto of every inquirer after truth, but for far different and better purposes than that which prompted the exclamation."—The late John S. Skinner.
- "A volume of extensive information, deep thought, high intelligence, and moreover of material utility."—London Morning Advertiser.
- "Emanating from an active intellect, remarkable for distinct views and sincere convictions."-Britannia.
- "'The Past, Present, and Future,' is a vast summary of progressive philosophy, wherein he demonstrates the benefit of political economy in the onward progress of mankind, which, ruled and directed by overwhelming influences of an exterior nature, advances little by little, until these exterior influences are rendered subservient in their turn, to increase as much as possible the extent of their wealth and riches."

 —Dictionnaire Universel des Contemporains. Par G. Vapereau. Paris,

Principles of Social Science.

CONTENTS.—Volume I. Of Science and its Methods—Of Man, the Subject of Social Science-Of Increase in the Numbers of Mankind -Of the Occupation of the Earth-Of Value-Of Wealth-Of the Formation of Society—Of Appropriation—Of Changes of Matter in Place
—Of M hanical and Chemical Changes in the Forms of Matter. Volume II. of Vital Changes in the Form of Matter—Of the Instrument
of Assoc.ation. Volume III. of Production and Consumption—Of
Accumulation—Of Circulation—Of Distribution—Of Concentration and Centralization-Of Competition-Of Population-Of Food and Population-Of Colonization-Of the Malthusian Theory-Of Commerce-Of the Societary Organization-Of Social Science.

"I have no desire here to reproach Mr. Malthus with the extreme lightness of his scientific baggage. In his day, biology, animal and vegetable chemistry, the relations of the various portions of the human organism, etc. etc., had made but little progress, and it is to the man organism, etc. etc., had made but little progress, and it is to the general ignorance in reference to these questions that we must, as I think, look for explanation of the fact that he should, with so much confidence, in reference to so very grave a subject, have ventured to suggest a formula so arbitrary in its character, and one whose hollowness becomes now so clearly manifest. Mr. Carey's advantage over him, both as to facts and logic, is certainly due in great part to the progress that has since been made in all the sciences connected with life; but then, how admirably has he profited of them! How entirely is he au courant of all these branches of knowledge which, whether

directly or indirectly, bear upon his subject! With what skill does he ask of each and every of them all that it can be made to furnish, whether of facts or arguments! With what elevated views, and what amplitude of means, does he go forward in his work! Above all, how thorough in his scientific caution! Accumulating inductions. and presenting for consideration facts the most undoubted and probabilities of the highest kind, he yet affirms nothing, contenting himself with showing that his opponent had no good reason for affirming the nature of the progression, nor the time of duplication, nor the generalization which takes the facts of an individual case and deduces from them a law for every race, every climate, every civilization, every condition, moral or physical, permanent and transient, healthy or unhealthy, of the various populations of the many countries of the world. Then, having reduced the theory to the level of a mere hypothesis, he crushes it to atoms under the weight of facts."—
M. De Fontenay in the "Journal des Economistes." Paris, September, 1862.

"This book is so abundantly full of notices, facts, comparisons, calculations, and arguments, that too much would be lost by laying a part of it before the eye of the reader. The work is vast and severe in its conception and aim, and is far removed from the common run of the books on similar subjects."—Il Mondo Letterario, Turin.

Philadelphia.

"His theory of Rents is regarded as a complete demonstration that the popular views derived from Ricardo are erroneous; and on the subject of Protection, he is generally confessed to be the master-thinker of his country."—Westminster Review.

"Both in America and on the Continent, Mr. Henry Carey has ac-

ant."-London Critic.

"Mr. Carey began his publication of Principles twenty years ago; he is certainly a mature and deliberate writer. More than this, he is readable: his pages swarm with illustrative facts and with American instances.

"We are in great charity with books which, like Mr. Carey's, theorize with excessive boldness, when the author, as does Mr. Carey, possesses information and reasoning power."-London Athenaum.

"Those who would fight against the insatiate greed and unscrupulous misrepresentations of the Manchester school, which we have frequently exposed, without any of their organs having ever dared to make reply, will find in this and Mr. Carey's other works an immense store of arms and ammunition. store of arms and ammunition.

"An author who has, among the political economists of Germany and France, numerous readers, is worth attentive perusal in England."—London Statesman.

- "Of all the varied answers to the old cry of human nature, 'Who will show us any good?' none are more sententious than Mr. Carey's. He says to Kings, Presidents, and People, 'Keep the nation at work, and the greater the variety of employments the better.' He is seeking and elucidating the great radical laws of matter as regards man. He is at once the apostle and evangelist of temporal righteousness." -National Intelligencer.
- "A work which we believe to be the greatest ever written by an American, and one which will in future ages be pointed out as the most successful effort of its time to form the great scientia scientiarum." -Philadelphia Evening Bulletin.

The Slave Trade, Domestic and Foreign;

CONTENTS.—The Wide Extent of Slavery—Of Slavery in the British Colonies—Of Slavery in the United States—Of Emancipation in the British Colonies—How Man passes from Poverty and Slavery toward Wealth and Freedom—How Wealth tends to Increase—How Labor acquires Value and Man becomes Free—How Man passes from Wealth and Freedom toward Poverty and Slavery—How Slavery grew, and How it is now maintained in the West Indies—How Slavery grew, and is maintained in the United States—How Slavery grows in Portugal and Turkey—How Slavery grows in India—How Slavery grows in Ireland and Scotland—How Slavery grows in England—How as Slavery be extinguished?—How Freedom grows in Northern Germany—How Freedom grows in Russia—How Freedom grows in Denmark—How Freedom grows in Spain and Belgium—Of the Duty of the People of the United States—Of the Duty of the People of England.

"As a philosophical writer, Mr. Carey is remarkable for the union of comprehensive generalizations with a copious induction of facts. His research of principles never leads him to the neglect of details, nor is his accumulation of instances ever at the expense of universal truth. He is, doubtless, intent on the investigation of laws, as the appropriate aim of science, but no passion for theory seduces him into the region of pure speculation. His mind is no less historical than philosophical, and had he not chosen the severer branch in which his studies have borne such excellent fruit, he would have attained an eminent rank among the historians from whom the literature of our country has received such signal illustration."—New York Tribune.

French Politico-Economic Controversy,

Between the Supporters of the Doctrines of Carey and of those of Ricardo and Malthus. By MM. De Fontenay, Dupuit, Baudrillart, and others. Translated from the "Journal des Economistes," 1862-63. (In press.)

Protection of Home Labor and Home Productions

Smith A Manual of Political Economy.

By D Peshine Smith 12mo., cloth......\$1.25









3 3125 01360 2012

